

Service Repair Sheet SRS68046

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Alex Ferguson

John Radcliffe Hospital

Clinical Engineering

01865572163

00004040

Alex.Ferguson@ouh.nhs.uk

19/Jan/2022

Robert Connor

Viamed

Quote

Notes 14/Jan/2022 Kate Griffiths

14/Jan/2022 Kate Griffiths

DB3 H0000427. Intensity control knob broken, I did mention he could buy that, but he would like it serviced etc so will send device in.

19/Jan/2022 Robert Connor

Received 1 x Microstim DB3 s/n H0000427

Ready For quote

CCGreen 25-1-2022

Repair Complete Signed

CCGreen 25-2-2022

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34635	Microstim DB3	2510000	H0000427	N

2540010 x 1 @ £45.
S/N, SRS, SRN

UPS x 1 @ £10.

S RS 68046

Repair Quotation Request

Date of request: 14/01/2022



Oxford University Hospitals
NHS Foundation Trust

Post to:

15 Station Road,
Cross Hills,
Keighley
BD20 7DT

Deliver To:

Clinical Engineering
Industrial Block
John Radcliffe Hospital
Headley Way
OX3 9DU

Telephone: 01865 221548

Email: Clinical.engineering@ouh.nhs.uk

The following item(s) of equipment are reported faulty and require testing/repair.

Brand: VIAMED

Model: MICROSTIM DB3

Serial No: H0000427

Asset No: 048001

The reported fault is:

Nerve Stimulator control knob broken and missing patient leads

Please carry-out an evaluation and forward a quotation to Clinical Engineering at the following address: Clinical.engineering@ouh.nhs.uk

Please include the **Job reference 601921** in all quotes and correspondence related to this request.

Kind regards,

Clinical Engineering

Service Repair Sheet 68046

Contact Name	Alex Ferguson
Company/ Hospital Name	John Radcliffe Hospital
Department	Clinical Engineering
Direct Phone	01865572163
Opera Account	00004040
Email	Alex.Ferguson@ouh.nhs.uk
Order Number	RTHN400121608
Date Received	19/Jan/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN34635	2510000	H0000427	Microstim DB3	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	2540010		
	Qty: 1	2510000		

The Microstim DB3 has been repaired. A new patient lead has been supplied.
