

Service Repair Sheet SRS68035

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Sudath Weeraman

Company/ Hospital Name

Prime Lanka

Department

Position

Direct Phone

9410718732285

General Phone

Opera Account

00006714

Email

sudathweeraman17@gmail.com

Order Number

Date Received

27/Jan/2022

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Warranty

Notes 22/Dec/2021 Sarah Walton

22/Dec/2021 Sarah Walton

Faulty sensor S/N: 608495 to be returned

27/Jan/2022 Robert Connor

1 x R24MED s/n 608495

Ready For quote

Repair Complete Signed

CG. Neen 28-2-22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34656	Oxygen Sensor	0110024	608495	Yes

0140013 x 1 FOC  
Old SIN, SRS, SRN

0110024 x 1 FOC  
New SIN, SRS, SRN

ExW - ship with next order  
cg 28-2-22



"Bringing quality to life."

No: 57/8, P.B. Alwis Perera Mawatha, Katubedda,  
Moratuwa, Sri Lanka.

+94 071 873 2285 / +94 011 345 9456

011 262 4324

primelanka07@gmail.com  
sudathweeraman17@gmail.com

10 January 2022

The Repair Team.

Viamed LTD, No.15, Station Road, Cross Hills, Keighley  
West Yorkshire, BD20 7DT  
United Kingdom.

Dear Sir,

The warranty replacement notice, for Oxygen sensor model R-24MED  
Please note below details for your reference.

Model – Oxygen Sensor R-24MED

1. S/N - 608495

Return Reference No. SRS-68035

Thank you,

You're faithfully

S.J. Weeraman

Prime Lanka Associates  
No.57/8, P.B. Alwis Perera Mawatha  
Katubadda, Moratuwa  
Sri Lanka.

Service Repair Sheet 68035

Contact Name

Sudath Weeraman

Company/ Hospital Name

Prime Lanka

Direct Phone

9410718732285

Opera Account

00006714

Email

sudathweeraman17@gmail.com

Date Received

27/Jan/2022

Booked in By

Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34656	0110024	608495	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110024

Replaced under warranty with S/N 778561

---