

Service Repair Sheet 68036
Contact Name Apostolos Atsalakis
Company/ Hospital Name Xhale
General Phone 00302109531294
Opera Account 00006401
Email apostolos@endomedical.co
Date Received 05/Jan/2022
Booked in By Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34494	0110081	667938	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778780

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34495	0110081	672004	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778783

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34498	0110081	672005	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778786

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34499	0110081	672007	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778793

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34500	0110081	672008	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778801

Service Repair Sheet 68036

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	Xhale
General Phone	00302109531294
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	05/Jan/2022
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34501	0110081	672010	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778811

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34502	0110081	672011	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778812

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34503	0110081	672012	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778821

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34504	0110081	672013	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778824

Service Repair Sheet 68036
Contact Name Apostolos Atsalakis
Company/ Hospital Name Xhale
General Phone 00302109531294
Opera Account 00006401
Email apostolos@endomedical.co
Date Received 05/Jan/2022
Booked in By Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34505	0110081	672016	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778828

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34506	0110081	672018	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778829

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34507	0110081	672019	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778831

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34508	0110081	672021	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778832

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34509	0110081	672024	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778833

Service Repair Sheet 68036
Contact Name Apostolos Atsalakis
Company/ Hospital Name Xhale
General Phone 00302109531294
Opera Account 00006401
Email apostolos@endomedical.co
Date Received 05/Jan/2022
Booked in By Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34510	0110081	672025	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778841

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34511	0110081	672026	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778845

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34513	0110081	672031	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778847

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34514	0110081	672039	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778848

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34515	0110081	672040	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778850

Service Repair Sheet 68036
Contact Name Apostolos Atsalakis
Company/ Hospital Name Xhale
General Phone 00302109531294
Opera Account 00006401
Email apostolos@endomedical.co
Date Received 05/Jan/2022
Booked in By Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34516	0110081	672041	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778851

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34517	0110081	681626	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778854

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34518	0110081	681635	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778860

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34519	0110081	681657	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778861

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34520	0110081	684319	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778865

Service Repair Sheet 68036
Contact Name Apostolos Atsalakis
Company/ Hospital Name Xhale
General Phone 00302109531294
Opera Account 00006401
Email apostolos@endomedical.co
Date Received 05/Jan/2022
Booked in By Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34521	0110081	684320	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778872

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34522	0110081	684327	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778873

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34523	0110081	684333	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778878

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34524	0110081	684346	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778901

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34525	0110081	684350	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778904

Service Repair Sheet 68036

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	Xhale
General Phone	00302109531294
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	05/Jan/2022
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34526	0110081	684362	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778921

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34527	0110081	684370	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778922
