

Service Repair Sheet 68041

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	XHALE S.A.
General Phone	+30 693 660 9908
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	12/Jan/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34585	0110081	689245	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 705413

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34586	0110081	689246	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 705414

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34587	0110081	689247	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 705415

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34588	0110081	689248	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 705424

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34589	0110081	689249	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 705426

Service Repair Sheet 68041

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	XHALE S.A.
General Phone	+30 693 660 9908
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	12/Jan/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34590	0110081	689250	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 705791

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34591	0110081	689251	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 705792

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34592	0110081	689252	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 705793

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34593	0110081	689253	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 705794

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34594	0110081	689254	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778645

Service Repair Sheet 68041

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	XHALE S.A.
General Phone	+30 693 660 9908
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	12/Jan/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34595	0110081	689255	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778646

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34596	0110081	689256	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778648

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34597	0110081	689257	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778650

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34598	0110081	689258	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778654

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34599	0110081	689259	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778658

Service Repair Sheet 68041

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	XHALE S.A.
General Phone	+30 693 660 9908
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	12/Jan/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34600	0110081	689260	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778660

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34601	0110081	689261	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778666

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34602	0110081	689264	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778667

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34603	0110081	689265	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778668

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34604	0110081	689266	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778669

Service Repair Sheet 68041

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	XHALE S.A.
General Phone	+30 693 660 9908
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	12/Jan/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34605	0110081	689267	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778671

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34606	0110081	689268	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778708

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34607	0110081	689269	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778711

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34608	0110081	689271	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778713

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34609	0110081	689272	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778719

Service Repair Sheet 68041

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	XHALE S.A.
General Phone	+30 693 660 9908
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	12/Jan/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34610	0110081	689274	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778722

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34612	0110081	689276	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778724

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34613	0110081	689277	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778725

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34614	0110081	689278	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778728

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34615	0110081	689279	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778731

Service Repair Sheet 68041

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	XHALE S.A.
General Phone	+30 693 660 9908
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	12/Jan/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34616	0110081	689280	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778733

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34617	0110081	689281	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778736

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34618	0110081	689282	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778738

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34619	0110081	689284	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778742

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34620	0110081	689285	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778744

Service Repair Sheet 68041

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	XHALE S.A.
General Phone	+30 693 660 9908
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	12/Jan/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34621	0110081	689286	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778745

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34622	0110081	689287	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778752

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34623	0110081	689288	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778756

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34624	0110081	689289	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778763

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34625	0110081	689290	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778770

Service Repair Sheet 68041

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	XHALE S.A.
General Phone	+30 693 660 9908
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	12/Jan/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34626	0110081	689291	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778771

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34627	0110081	689292	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778772

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34628	0110081	689293	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778773

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34629	0110081	689294	Oxygen Sensor	

Return Unrepaired

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 778776
