

## Service Repair Sheet 67984

Contact Name	Amanda Richardson
Company/ Hospital Name	Medivent Ltd (Euro)
Direct Phone	0035316280338
General Phone	00353 16280338
Opera Account	00007374
Email	office@medivent.ie
Order Number	7378
Date Received	04/Nov/2021
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	
SRN34324	0111235	329809	Oxygen Monitor	Complete - Repaired Time :0 Hour(s)

## Parts Replaced

Qty: 1	0180005
Qty: 1	0100120

The MX300 Oxygen monitor has been repaired. The PCB has been replaced.

---

Repair	Ref	S/N	Equipment Type	
SRN34325	0131202	0010709	Oxygen Monitor Cable	No Fault Found Time :0 Hour(s)

The Oxygen sensor cable has been tested. No fault was found.

---

Repair	Ref	S/N	Equipment Type	
SRN34326	0110017	134695	Oxygen Sensor	End Of Life Time :0 Hour(s)

## Parts Replaced

Qty: 1	0110017
--------	---------

The R-17MED Oxygen sensor has been replaced with SN:688487.

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34327	0110017	566049	Oxygen Sensor	Time :0 Hour(s)

## Parts Replaced

Qty: 1	0110017
--------	---------

The R-17MED Oxygen sensor has been replaced under warranty with SN:688488.

---