

Service Repair Sheet 68096

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	Xhale
General Phone	00302109531294
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	05/Jan/2022
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34528	0110081	684376	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778820

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34530	0110081	684380	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778823

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34531	0110081	684381	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778839

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34532	0110081	684389	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778858

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34533	0110081	684399	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778862

Service Repair Sheet 68096

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	Xhale
General Phone	00302109531294
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	05/Jan/2022
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34534	0110081	684407	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778866

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34536	0110081	684441	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778889

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34537	0110081	689220	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778894

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34538	0110081	689223	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778896

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34539	0110081	689224	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778899

Service Repair Sheet 68096

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	Xhale
General Phone	00302109531294
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	05/Jan/2022
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34540	0110081	689228	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778903

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34541	0110081	689230	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778913

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34542	0110081	689233	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778914

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34543	0110081	689236	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:778917