

Ready For quote

Repair Complete Signed

CANEON 14.3.22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34528	Oxygen Sensor	0110081	684376	Yes
SRN34530	Oxygen Sensor	0110081	684380	Yes
SRN34531	Oxygen Sensor	0110081	684381	Yes
SRN34532	Oxygen Sensor	0110081	684389	Yes
SRN34533	Oxygen Sensor	0110081	684399	Yes
SRN34534	Oxygen Sensor	0110081	684407	Yes
SRN34536	Oxygen Sensor	0110081	684441	Yes
SRN34537	Oxygen Sensor	0110081	689220	Yes
SRN34538	Oxygen Sensor	0110081	689223	Yes
SRN34539	Oxygen Sensor	0110081	689224	Yes
SRN34540	Oxygen Sensor	0110081	689228	Yes
SRN34541	Oxygen Sensor	0110081	689230	Yes
SRN34542	Oxygen Sensor	0110081	689233	Yes
SRN34543	Oxygen Sensor	0110081	689236	Yes

0140013 x 14 FOC
old S/N, SRS, SRN.

0110081 x 14 FOC
New S/N's, SRS, SRN.

0140015 Cg 14.3.22.

~~0140014~~ x 2 FOC

- Not under warranty.

Returning as agreed with Apostolos Atsalakis

S/N 689275 SRS 68094, SRN 34611.

S/N 672028 SRS 68095, SRN 34512.

UPS x 1 FOC.

SRN	Equipment	Stock Reference	Serialnumber Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN34512	Oxygen Sensor	0110081	1887493	672028	Oxygen sensor, UFO 130-2	No	No	Unfinished		00:00
SRN34512 Customer Notes: Unstable output										

Currently Viewing ITEM SRN34512 Oxygen Sensor 0110081 672028 Oxygen sensor, UFO 130-2

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	02/Mar/2022 Catherine Spence Clip where wing should be is broken 02/Mar/2022 Catherine Spence New Warranty Flagged OFF Part of clip is broken	Non added Yet

CG 14.3.22
 0140015 x 1 FOC
 SIN, SRS, SRN

Please see combined
 order on
 SRS 68096 CG 14.3.22.

Move SRN34575 From SRS68041 To SRS68055
 Move SRN34576 From SRS68041 To SRS68055
 Move SRN34577 From SRS68041 To SRS68055

05/Feb/2022 Catherine Spence
 Test results for these sensors are attached to this srs
 07/Feb/2022 Philip Crossley
 All tested now
 09/Feb/2022 Catherine Spence
 waiting on new stock to arrive , also waiting on report from Teledyne on other sensors
 that have already been returned from other SRS's, Steve Nixon to advise
 16/Feb/2022 Catherine Spence
 engineers room
 22 /02 / 2022 Catherine Spence
 Moving from SRS68041 to new SRS for replacement purposes as part of a part
 shipment. cg 20220222
 Move SRN34578 From SRS68041 To SRS68085
 Move SRN34579 From SRS68041 To SRS68085
 Move SRN34580 From SRS68041 To SRS68085
 Move SRN34581 From SRS68041 To SRS68085
 Move SRN34582 From SRS68041 To SRS68085
 Move SRN34583 From SRS68041 To SRS68085
 Move SRN34584 From SRS68041 To SRS68085

 03 /03 / 2022 Catherine Spence
 Moving to new SRS due to connector broken
 Move SRN34611 From SRS68041 To SRS68094

Items for Repair

...

SRN	Equipment	Stock Reference	Serialnumber Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN34611	Oxygen Sensor	0110081	1903362	689275	Oxygen sensor, UFO 130-2	No	No	Unfinished		00:00

Currently Viewing ITEM SRN34611 Oxygen Sensor 0110081 689275 Oxygen sensor, UFO 130-2

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	Non added Yet	Non added Yet

-cg 14-3-22
 0140015 x 1 FCC
 SIN, SRS, SRN

please see combined
 order on SRS 68096.
 cg 14-3-22