

(add separately to completing a repair)

Notes Customer will read

Quote Preview

Repair SRS68121 Values in Pounds @ £1: £1.00

SRN34928	Foetal Simulator	1410000			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		1480001	1	◆35.00	◆35.00
				Parts Cost	◆35.00

Add Blank Line For new item linked to repair

SRN	Equipment	Reference	Serialnumber Barcode	Serialnumber	Description	Customer Warranty New	Customer Warranty Repair	Our Supplier Warranty	Status	History
SRN34928	Foetal Simulator	1410000	1447282	PR02912A12		No Change	No Change	<input checked="" type="checkbox"/> Check	Quote	History

SRN34928 Foetal Simulator 1410000 PR02912A12

Global fill fields across multiple 1410000's records on SRS

Create Issue - Use to link files and or photos to the SRS

Internal Engineer Notes against SRN34928

30/Mar/2022 Michael Green

A calibration test has been performed on the V1000. The unit is operating within specification. A certificate has been produced (1648641626). No further work was necessary the unit was in good condition.

30/Mar/2022 Michael Green

The warranty seal has been replaced with number 101133.

Add Engineer Notes