



Mid Georgia Diving LLC

CID20138 Opera CID20138 Type:Vandagraph Trade
Mid Georgia Diving LLC 1117 Thomason Road, , Monticello, , GA
 31064, USA
 Tel +1 706 318 0269 [Log Call](#)
 Proforma

[Account Home](#)
[Main Details](#)
[Account Memos](#)
[Sales History](#)
[Stock References](#)
[Customer Returns](#)
[Service Visits](#)
[Distributor Agreements](#)

[Documents Files](#)
[Linked Issues](#)
[Regulatory Agreements](#)

SRS68084

[Print Barcodes](#)
[Print A4 Sheet](#)
[Split Items into Different SRS Numbers](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Handle with care
 Add Items to Supplier Returns Box

[Add](#)

- ☐ Return for Credit / Return to Stock
 Unopened - will apply to all items on srs
☐ Clear From System - Force from System.
 - will apply to all items on srs

Add notes to SRS

[Add Notes](#)

Service Repair Sheet 68084		Notes
Company / Hospital	Mid Georgia Diving LLC	21/Feb/2022 Ryan Swaine
Contact Name	Robert Billings	21/Feb/2022 Ryan Swaine
Department		Mk.1 VN202 IANTD model - Power switch requires replacing and general check over.
Position		21/Mar/2022 Robert Connor
Company Phone	+1 706 318 0269	Received 1 x VN202 s/n VN 2536, with sensor, s/n unknown.
Direct Phone	+1 706 318 0269	21/Mar/2022 Robert Connor
Opera Account	CID20138	Battery compartment appears to show some evidence of battery leakage, power button is detached from case, sensor provided appears very old, serial number has completely worn away.
Email	midgadiving@gmail.com	23/Mar/2022 Catherine Spence
Order Number		in engineers room
Viamed ORD Number		
Date	21 Mar 2022	

Received Into building	
Type	Quote Before Repair
Issues?	

Items for Repair

SRN	Equipment	Stock Reference	Serialnumber Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN34817	Oxygen Analyser VN202			VN 2536	VN202	No	No	Unfinished		00:00

Currently Viewing ITEM SRN34817 Oxygen Analyser VN202 VN 2536 VN202

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	Non added Yet	Non added Yet