



The Dive Warehouse

CID6984 Opera WAREHOU Type:Vandagraph Trade

The Dive Warehouse 6 Anton Inglott Street, Msida, , 1180, Malta

Tel +356 27658035

Log Call

Credit 30 Days after date of invoice

Account Home
 Main Details
 Account Memos
 Sales History
 Stock References
 Customer Returns
 Service Visits
 Distributor Agreements

Documents Files
 Linked Issues
 Regulatory Agreements

SRS68112

[Print Barcodes](#)[Print A4 Sheet](#)[Split Items into Different SRS Numbers](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description

Choose a file to upload: No file chosen

Next

Handle with care

Add Items to Supplier Returns Box

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Service Repair Sheet 68112

Company / Hospital	The Dive Warehouse
Contact Name	Claude Sciberras
Department	
Position	
Company Phone	+356 27658035
Direct Phone	+356 27658035
Opera Account	WAREHOU
Email	ctclaud@gmail.com
Order Number	
Viamed ORD Number	
Date Received Into building	31 Mar 2022
Type	Quote Before Repair
Issues?	257009

Notes

18/Mar/2022 Ryan Swaine

18/Mar/2022 Ryan Swaine

TEK-OX - Faulty Screen

31/Mar/2022 Robert Connor

Received 1 x tek ox s/n TX 2909

LINKED ISSUE NOTES:

[257009:](#)

AutoGenerated Issue SRS68112 Appears to be Complete

Items for Repair

SRN	Equipment	Stock Reference	SerialNumber Barcode	SerialNumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
-----	-----------	-----------------	----------------------	--------------	-------------	--------------	-----------------	--------	-------------	------------

SRN34930	Vandagraph Tek Ox	7910211	1274434	TX2909	Oxygen Analyser Tek-Ox	No	No	Complete - Repaired	Not Switching On	00:30
--------------------------	----------------------	---------	---------	--------	------------------------------	----	----	---------------------------	------------------------	-------

Currently Viewing ITEM SRN34930 Vandagraph Tek Ox 7910211 TX2909 Oxygen Analyser Tek-Ox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Tek-Ox analyser has been repaired. The PCB has been replaced.	<p>05/Apr/2022 Michael Green The Tek-Ox analyser has been tested. The PCB is not powering up. The rest of the unit is in good condition.</p> <p>05/Apr/2022 Michael Green The unit serial number is TX2909, the PCB serial number is 3101.</p> <p>11/Apr/2022 Michael Green The Tek-Ox analyser has been repaired. The PCB has been replaced.</p>	The Tek-Ox analyser has been repaired. The PCB has been replaced.