

Service Repair Sheet 68143

Contact Name	Kinga Frolyo
Company/ Hospital Name	H.S Medplan KFT (EURO)
Direct Phone	+36 1 361 0136
General Phone	+361 01363610272
Opera Account	00006106
Email	kinga.frolyo@medplan.hu
Date Received	28/Apr/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35017	0110022	622758	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110022

Replaced under warranty with S/N 786501

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35018	0110022	622759	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110022

Replaced under warranty with S/N 786502

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35019	0110022	624826	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110022

Replaced under warranty with S/N 786503