

Service Repair Sheet SRS68127

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Daniel Lodge

Royal Liverpool University Hospital

Medical Engineering Department

01517062079

0151 706 2000

00002690

daniel.lodge@liverpoolft.nhs.uk

06/Apr/2022

Robert Connor

Viamed

Warranty

Notes 01/Apr/2022 Steve Hardaker

01/Apr/2022 Steve Hardaker

Returning a AX300, s/n 339165, for repair under warranty. Some of the LCD segments are failing.

06/Apr/2022 Robert Connor

Received 1 x AX300 s/n 339165, with coiled cable 0010409, and sensor 566274, plus flow diverter.

Ready For quote

Repair Complete Signed

CGreen 10.5.22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34939	Oxygen Monitor	0111230	339165	Yes
SRN34940	Oxygen Monitor Cable	0131202	0010409	Yes
SRN34941	Oxygen Sensor	0110017	566274	Yes

0140006 x 1 FOC
S/N, SRS, SRN.

0140025 x 1 FOC
NO fault found.
S/N, SRS, SRN

0140011 x 1 FOC
NO fault found
S/N, SRS, SRN

10PS x 1 FOC

Service Repair Sheet 68127

Contact Name	Daniel Lodge
Company/ Hospital Name	Royal Liverpool University Hospital
Department	Medical Engineering Department
Direct Phone	01517062079
General Phone	0151 706 2000
Opera Account	00002690
Email	daniel.lodge@liverpoolft.nhs.uk
Date Received	06/Apr/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34939	0111230	339165	Oxygen Monitor	Complete - Repaired Time :0 Hour(s)

The AX300 Oxygen analyser has been repaired. The display now shows all segments.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34940	0131202	0010409	Oxygen Monitor Cable	No Fault Found Time :0 Hour(s)

The Oxygen sensor cable has been tested. No fault was found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34941	0110017	566274	Oxygen Sensor	No Fault Found Time :0 Hour(s)

The R-17MED Oxygen sensor has been tested. No fault was found.
