

Service Repair Sheet SRS68146

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Chris Kavanagh

Just Inc Limited

07738828787

chris@thinairsports.com

05/May/2022

Robert Connor

Viamed

Warranty

Notes 28/Apr/2022 Kate Griffiths

28/Apr/2022 Kate Griffiths

Pulse Oximetry Silicone Finger Sensor s/n: Cen10005 - ``just stopped working, the red light has gone out``. Purchased March 2021

05/May/2022 Robert Connor

Received 1 x 0014754 s/n CEN10005

Ready For quote

Repair Complete Signed

CGREEN 11-5-22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35033	Pulse Oximetry Finger Sensor	0014754	CEN10005	Yes

0040003 x 1 FOC.
old SN, SRS, SRN

0014754 x 1 FOC
new SN, SRS, SRN

UPS x 1 FOC.

Service Repair Sheet 68146

Contact Name

Company/ Hospital Name

Direct Phone

Email

Date Received

Booked in By

Chris Kavanagh

Just Inc Limited

07738828787

chris@thinairsports.com

05/May/2022

Robert Connor

Repair Ref S/N
SRN35033 0014754 CEN10005

Equipment Type
Pulse Oximetry Finger Sensor

Under Warranty

Time :0 Hour(s)

Parts Replaced

Qty: 1 0014754

Serviced by Q.A. by

Repair Report:

The SpO2 Silicone Finger Sensor has been replaced under warranty with SN:CEN10015.
