

Service Repair Sheet SRS68108

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Ana Laura Hernandez

Company/ Hospital Name

Prindugas S.A. DE C.V.

Department

Position

Direct Phone

+525510501576

General Phone

+525 573 145623

Opera Account

00006723

Email

prindugasana@gmail.com

Order Number

Date Received

21/Mar/2022

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Warranty

Notes Customer has some faulty sensors that they want to return for investigation.

21/Mar/2022 Robert Connor

Received 9 x R-21A s/n 608262, 608267, 608269, 608272, 608281, 608361, 608371, 608373, 669463

Ready For quote

Repair Complete Signed

Green 19-5-22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34808	Oxygen Sensor	0110121	608262	Yes
SRN34809	Oxygen Sensor	0110121	608267	Yes
SRN34810	Oxygen Sensor	0110121	608269	Yes
SRN34811	Oxygen Sensor	0110121	608272	Yes
SRN34812	Oxygen Sensor	0110121	608281	Yes
SRN34813	Oxygen Sensor	0110121	608361	Yes
SRN34814	Oxygen Sensor	0110121	608371	Yes
SRN34815	Oxygen Sensor	0110121	608373	Yes
SRN34816	Oxygen Sensor	0110121	669463	Yes

0140013 x 9 @ EO
old SIN'S, SRS, SRN.

0110121 x 9 @ EO
New SIN, SRS, SRN

EXW : DHL Ship with CUMI35955

CARTA FACTURA COMMERCIAL INVOICE

México, D.F. March 16th, 2022

De (Remitente) / From (Shipper)
Nombre: Ana Laura Hernandez Urbano
Empresa: Prindugas S.A de C.V
Dirección: Moctezuma #448, col. Churubusco Tepeyac, Del. Gustavo A. Madi
Ciudad: CdMx **C.P.** 07730 **Teléfono:** 5532330567

Para (Destinatario) / To Company
Name: Sarah Walton
Company Name: Viamed Ltd
Address: 15 Station Road, Cross Hills, Keighley BD20 7DT, United Kingdom
City: Keighley **Z.C.** BD20 7DT **PH** 44 (0)1535 634542

Descripción detallada del envío			
Cantidad	Descripción	Costo	Moneda
9	Sensor de oxígeno automotriz R-21A	2,280.42	MXN

Detailed description of the Shipment			
Unit	Description	Cost	Currency
9	Automotive Oxygen Sensor R-21A	111.24	USD

Propósito del envío

- ☐ Venta
- ☐ Regalo no solicitado
- ☐ Muestra sin valor comercial
- ☐ Muestra mutilada y/o marcadas para no venta
- ☐ Promoción
- ☐ Análisis
- ☐ Retorno al origen por olvido
- ☒ Para reparación
- ☐ Por sustitución y/o en garantía
- ☐ Exhibición / exposición y/o Convención Internacional
- ☐ Otros

Purpose of Shipment

- ☐ Sale
- ☐ Unsolicited Gift
- ☐ Samples without commercial value
- ☐ Mutilated or marked samples not for resale
- ☐ Promotional Material
- ☐ Analysis
- ☐ Return to origin (forgotten)
- ☒ For repair
- ☐ For change in guaranty or defective material
- ☐ International Show / convention / exhibition or display
- ☐ Others

Valor para fines aduanales \$ 2,280.42 M.N.
Value for customs purpose \$ 111.24 U.S.D.

¿Requiere Pedimento? No ☐ Sí ☒ **Temporal** ☐ **Definitivo** ☒

Firma del Remitente/Shipper's Signature

DHL AWB:

Bajo protesta de decir verdad declaro que los valores asentados en el presente documento son los que rigen al momento de su exportación y que he leído la parte trasera de esta hoja / I declare that the information stated in this invoice is true and correct.

EXW : DHL Ship with CUMI35955

Service Repair Sheet 68108

Contact Name	Ana Laura Hernandez
Company/ Hospital Name	Prindugas S.A. DE C.V.
Direct Phone	+525510501576
General Phone	+525 573 145623
Opera Account	00006723
Email	prindugasana@gmail.com
Date Received	21/Mar/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34808	0110121	608262	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110121

Replaced under warranty with S/N 807483

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34809	0110121	608267	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110121

Replaced under warranty with S/N 807484

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34810	0110121	608269	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110121

Replaced under warranty with S/N 807485

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34811	0110121	608272	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110121

Replaced under warranty with S/N 807486

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34812	0110121	608281	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110121

Replaced under warranty with S/N 807487

Service Repair Sheet 68108

Contact Name	Ana Laura Hernandez
Company/ Hospital Name	Prindugas S.A. DE C.V.
Direct Phone	+525510501576
General Phone	+525 573 145623
Opera Account	00006723
Email	prindugasana@gmail.com
Date Received	21/Mar/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34813	0110121	608361	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110121

Replaced under warranty with S/N 807488

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34814	0110121	608371	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110121

Replaced under warranty with S/N 807489

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34815	0110121	608373	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110121

Replaced under warranty with S/N 807490

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34816	0110121	669463	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110121

Replaced under warranty with S/N 807491