

Service Repair Sheet SRS68171

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

John Rattigan

Furness General Hospital

Medical engineering

01229614115

01229 870 870

00002471

john.rattigan@mbht.nhs.uk

24/May/2022

Robert Connor

Viamed

Warranty

Notes 18/May/2022 Zoey Teal

18/May/2022 Zoey Teal

Sending in one MAXO2+AE as the readings are out. Reading 51% only, even when set to 100. Serial number GC66699018

24/May/2022 Robert Connor

Received 1 x MAX-O2+AE s/n GC66699018, with sensor s/n GL08399211 and flow diverter

Ready For quote

Repair Complete Signed

CGreen 26.5.2022

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35062	Oxygen Monitor	0111261	GC66699018	Yes
SRN35063	Oxygen Sensor	0110429	GL08399211	Yes

0140000 x 1 @ £0.

SIN, SRS, SRN NO FAULT FOUND ;

0140013 x 1 @ £0

old SIN, SRS, SRN

0110429 x 1 @ £0

new SIN, SRS, SRN

UPS x 1 @ £0.



University Hospitals of Morecambe Bay
NHS Foundation Trust
Medical Engineering Department



REPAIR UNDER WARRANTY

Job Reference 323493 Date : 18/05/2022

Equipment Details

Asset Number 232248
Serial Number GC66699018
Description MAXTEC MAXO2+AE OXYGEN ANALYSER TEST EQUIPMENT
Department FGH SOUTH LAKES BIRTH CENTRE-DELIVERY
Fault / Additional Info Not reading correctly

WARRANT REPAIR - REF SRS 68171

Action Required

Please find enclosed the above faulty unit requiring repair.

We believe this unit to be under warranty.

PLEASE SEND ANY CORRESPONDENCE TO THE EMAIL ADDRESSES BELOW

john.rattigan@mbht.nhs.uk
and cc medical.engineering@mbht.nhs.uk

Declaration

This equipment has been decontaminated in accordance with the Trusts Equipment Decontamination Policy.

Signature _____

Return Address

John Rattigan
Medical Engineering
Furness General Hospital
Dalton Lane
Barrow
LA14 4LF
Tel : 01229 614115

Service Repair Sheet 68171

Contact Name	John Rattigan
Company/ Hospital Name	Furness General Hospital
Department	Medical engineering
Direct Phone	01229614115
General Phone	01229 870 870
Opera Account	00002471
Email	john.rattigan@mbht.nhs.uk
Date Received	24/May/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35062	0111261	GC66699018	Oxygen Monitor	No Fault Found Time :0 Hour(s)

The MAXO2+AE Oxygen monitor has been tested. The unit is working as expected. No fault was found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35063	0110429	GL08399211	Oxygen Sensor	Time :0 Hour(s)

Parts Replaced
Qty: 1 0110429

The MAX-250E Oxygen sensor has been replaced under warranty with SN:GL08399223.
