



Casco Antiguo Comercial S.L.

 CID14659 Opera CID14659 Type: **Vandagraph Trade**
Casco Antiguo Comercial S.L. Calle De Senda Galiana, C - No.16-18 ,
 Coslada, Madrid, , 28821, Spain
 Tel **0034 911510250**  [Log Call](#)
 Credit 30 Days after date of invoice VAT ESB79683579

 Account Home

 Main Details

Account Memos

 Sales History

Stock References

Customer Returns

 Service Visits

Distributor Agreements

Documents
Files

 **Linked Issues**

Regulatory Agreements

SRS68181

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

Handle with care

Add Items to Supplier Returns Box

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Service Repair Sheet 68181		Notes
Company / Hospital	Casco Antiguo Comercial S.L.	26/May/2022 Ryan Swaine
Contact Name	Enrique Diaz Nunez	26/May/2022 Ryan Swaine
Department		Tek-Ox sn: TX3299. Purchase June 2021. reading low, customer fitted brand new sensor and still reading low; 46% in O2
Position	Technical Assistance Service	06/Jun/2022 Robert Connor
Company Phone	0034 911510250	Received 1 x tek-ox s/n TX 3299, with hard yellow case and blue t-adapter.
Direct Phone	+34 911510250	
Opera Account	CID14659	
Email	sat@cascoantiguo.com	
Order Number		
Viamed ORD Number		
Date Received Into building	06 Jun 2022	
Type	Warranty	
Issues?	262895	

Items for Repair

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN35078	Vandagraph	7910201		TX3299	Oxygen Analyser	Yes	No	No	No	00:00

Tek Ox	 1663175	Tek-Ox + Quick-Ox	Fault Found	Fault Found
SRN35078 Engineer Notes: INTERNAL NOTES not for customer discussion 10/Jun/2022 Michael Green The Tek-Ox analyser has been tested with the supplied sensor. The unit read normally in air and Oxygen. No low reading was seen. 13/Jun/2022 Michael Green The test has been repeated. The unit still read correctly in air and Oxygen. No fault was found.				

Currently Viewing ITEM SRN35078 Vandagraph Tek Ox 7910201 TX3299 Oxygen Analyser Tek-Ox + Quick-Ox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Tek-Ox analyser has been tested with the supplied sensor. The unit read normally in air and Oxygen. No low reading was seen. No fault was found.	10/Jun/2022 Michael Green The Tek-Ox analyser has been tested with the supplied sensor. The unit read normally in air and Oxygen. No low reading was seen. 13/Jun/2022 Michael Green The test has been repeated. The unit still read correctly in air and Oxygen. No fault was found.	The Tek-Ox analyser has been tested with the supplied sensor. The unit read normally in air and Oxygen. No low reading was seen. No fault was found.

⏏