

Service Repair Sheet SRS68177

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Maria Iglesias

Company/ Hospital Name

Proyectos Hospitalarios

Department

Position

Direct Phone

+34 914261712

General Phone

0034 914261712

Opera Account

00006673

Email

maria.iglesias@prhoinsa.com

Order Number

Date Received

06/Jun/2022

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Warranty

Notes 24/May/2022 Ryan Swaine

24/May/2022 Ryan Swaine

2x T-7 Sensors, sn 590801 and 590802. Not working in vent that uses MOX-4, so they should work. To test and let RS know if they pass or not.

06/Jun/2022 Robert Connor

Received 2 x T-7 s/n 590801, 590802, with flow diverters

Ready For quote

Repair Complete Signed

Careen 15.6.2022

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35076	Oxygen Sensor	0110057	590801	Yes
SRN35077	Oxygen Sensor	0110057	590802	Yes

0140013 x 2
old SIN'S, SRS, SRN

0110057 x 2
new SIN, SRS, SRN

EXW - please ask customer if they want sending now
or with next order.

if now we will have to change carriage
line.
C9 15.6.22

TECHNICAL SERVICE DEPARTMENT

COMPANY: Viamed Ltd

ADDRESS: 15 Station Road. Cross Hills. Keighley. West Yorkshire BD20 7DT. UK

CONTACT PERSON: Ryan Swaine

DATE: 25/05/2022

RETURN GOODS AUTHORIZATION NUMBER: N/A

☒ ON WARRANTY

☐ OUT WARRANTY

REFERENCE	SERIAL NUMBER	DETAILED PROBLEM DESCRIPTION (FAULT OBSERVED // REMEDIES ATTEMPTED)
T7	590801 590802	The readings that the cell give is always above of the FiO2 marked.



Maria Iglesias
Technical Service
Phone: +34 91 426 17 12
Fax: +34 91 431 26 58
Cell: +34 608 809 499

Service Repair Sheet 68177

Contact Name

Maria Iglesias

Company/ Hospital Name

Proyectos Hospitalarios

Direct Phone

+34 914261712

General Phone

0034 914261712

Opera Account

00006673

Email

maria.iglesias@prhoinsa.com

Date Received

06/Jun/2022

Booked in By

Robert Connor

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN35076

0110057

590801

Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1

0110057

Replaced under warranty with S/N 648538

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN35077

0110057

590802

Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1

0110057

Replaced under warranty with S/N 648539
