

Service Repair Sheet SRS68207

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Andrew Stacey

Smit Mobile Equipment

Service Engineer

0127664490

00020025

20/Jun/2022

Robert Connor

Viamed

Quote

Please email
copy of quote
to Mark Phipps

O/N:

AT8533

Given over the
phone by Andrew
cg. 20/6

Notes 20/Jun/2022 Steve Hardaker

20/Jun/2022 Steve Hardaker

Has 2 MX300 that require checking and repair, is bringing in by hand today:

- s/n 331753 - Won't calibrate, generated a lot of faults in recent weeks but the users didn't note the fault codes.

- s/n 332862 - Draining batteries in days, batteries had leaked so may have internal damage.

Please quote for repair to his colleague mark.phipps@smit.eu and also advise cost of MaxO2ME replacement in case repairs are too costly.

20/Jun/2022 Catherine Spence

s/n: 332862 unit was wet around the battery compartment, new batteries added today by customer.

Would like to try and collect tomorrow if possible

20/Jun/2022 Robert Connor

Received 2 x MX300 s/n 331753, 332862, with 3 x AA battery.

Ready For quote

CGreen 20.6.22.

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35096	Oxygen Monitor	0111235	331753	N
SRN35097	Oxygen Monitor	0111235	332862	N

0140005 @ £90 per hr = 0.5 hr = £45. - SRN35096
S/N, SRS, SRN


0100160 x 1 @ £105 - SRN35097
SRS, SRN

0140005 x 1 @ £0. - SRN35096
S/N, SRS, SRN
NO fault found.

~~EXW~~ EXW: collect in person.

Catherine Spence Required Reading 29 Issues 23 Unread 21 ISO Tasks | H/W: CH
 EC KG ML Future Active Users 21.00 °C

▼ Search



Select Currency

Pounds| Euros| Usd

Repair SRS68207 Values in Pounds @ £1: £1.00

SRN35097	Oxygen Monitor	0111235			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0100160	1	£105.00	£105.00
		0140005	0.5	£10 £0.00	£0.00
				Parts Cost	£105.00

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent

Andrew to go ahead
with repair.

AT8533

Alfer.