

Service Repair Sheet SRS68199

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Komal Gohil

Company/ Hospital Name

Muscat Pharmacy LLC

Department

Engineering

Position

Direct Phone

+968 24814501

General Phone

00968 99378612

Opera Account

00007020

Email

komal\_gohil@mpmct.com

Order Number

222960

Date Received

04/Jul/2022

Booked in By

Robert Connor

Main Company

Viamed

Type Return

For Servicing

Notes 10/Jun/2022 Ryan Swaine

11/Jun/2022 Ryan Swaine

1000 for Service and calibration certificate - part no. 1480000 USD46.75 EXW. SN: PR01974A12

12/Jun/2022 Sophie Lines

13/Jun/2022 Sophie Lines

14/Jun/2022 Sophie Lines

Customer would like the calibrated unit to be sent back with their order CVM137867 - please see email attached

15/Jun/2022 Catherine Spence

Account on stop, do not proceed until Helen has told us that the account has been paid.

16/Jul/2022 Robert Connor

Received 1 x V1000 s/n PR0197A12, with grey silicone cover and blue fabric carry case.

17/Jul/2022 Philip Crossley

130309 Transducer interface cushion is free with service

Ready For quote

Repair Complete Signed

CGNEEN 8.7.22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35115	Foetal Simulator	1410000	PR01974A12	

14800000 x 1 \$46.75

SN, SRS, SRN

Ship with  
CVM137867  
Carriage charge  
on above  
order @ 8%

UPS x 1

Shipping with CVM137867



## PURCHASE ORDER

Supplier	Order Details
TO : VIAMED LTD U.K.	Order Reference : 222960/ENGG/MPH/KG
ATTN : RYAN SWAINE	Date : 22/JUN/2022
CC : KOMAL GOHIL (OMAN) / HARISH MISTRY (OMAN)	Supplier Offer : E-mail dtd. 06 <sup>th</sup> June 2022 – Ref. No. SRS68199

Ship Mode	Ship Terms	Currency	Shipment Arr.
COURIER		USD	AS SOON AS POSSIBLE

  

Sl.No.	Description	Qty	Price	Total
1	V1000 SERVICE WITH CERTIFICATE OF CALIBRATION P/NO. 1480000 (S/N. PR01974A12) - Reference number SRS68199	1	46.75	46.75
TOTAL				46.75

*Ministry of Health, Oman has implemented online clearance system (Import Control) wherein all the invoices pertaining to Medical Devices require Health Authority approval in order to clear the shipment by customs.*

- Invoice in PDF (separately without any shipping documents) is required for submission. Multiple invoices in one PDF are also not allowed.*
- Product description must be clearly mentioned in the invoice.*
- All medical device (New Product/Any Changes) need to be listed at least 10 working days prior to shipping. You may Contact Ms. Nijun Joel ([nijun@mpmct.com](mailto:nijun@mpmct.com)) if you need any further queries.*
- All invoices for clearance must be forwarded to [device.clearance@mpmct.com](mailto:device.clearance@mpmct.com) at least five working days prior to the possible date of the shipment's arrival.*
- Please add the correct scientific name of the Medical Device.*
- Limit the number of products in one invoice to maximum 20 products only.*
- The invoice for medical device should be separate and not to be clubbed with pharmaceutical products and medicated medical devices.*
- Copy of Ministry of Environment Permit (wherever applicable) must be provided along with the invoice for MoH submission.*

### TERMS & CONDITION :

- Please accept this e-mail as our "Confirmed Order" and let us know once the unit is calibrated, so that we can arrange collection.
- Please mention HS Code against each and every item in your order confirmation / advance Invoice, enabling us to take prior approval from customs authorities, to avoid any delay in the clearance of goods. Also, we would like to inform you that a copy of Certificate of Origin should be attached with the Airway Bill / Bill of Lading for all shipment moving either through sea or air, to be submitted to the customs authorities, which will enable us to clear

Service Repair Sheet 68199

Contact Name	Komal Gohil
Company/ Hospital Name	Muscat Pharmacy LLC
Department	Engineering
Direct Phone	+968 24814501
General Phone	00968 99378612
Opera Account	00007020
Email	komal_gohil@mpmct.com
Order Number	222960
Date Received	04/Jul/2022
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Complete - Repaired
SRN35115	1410000	PR01974A12	Foetal Simulator	Time :0 Hour(s)

V1000 has had transducer interface cushion replaced and calibration has been checked

---