Service Repair Sheet SRS68115

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Aleksandre Basilashvili

LTD B Company

+995 5144 59090

CID17897

a29basco@hotmail.com

26/Jul/2022

Robert Connor

Viamed

Quote

Notes 23/Mar/2022 Zoey Teal 23/Mar/2022 Zoey Teal Sending in a faulty R-22A sensor. Serial number 606401 23/Jun/2022 Zoey Teal Customer is still sending this back 26/Jul/2022 Robert Connor

Ready For quote

Received 1 x R22A s/n 606401

Repair Complete Signed

Proforma?

een 27.7.22

Ç

Warranty Serial Number Stock Ref Equipment SRN 606401 0110122 Oxygen Sensor SRN35154

0110122 × 1 @ \$32.90 SRS, SRN.

23x15x12cm 0-20kg



Select Currency

Pounds Euros Usd

Repair SRS68115 Values in Dollars @ \$1.23090: • 1.00

SRN35154	Oxygen Sensor	0110122			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0110122	1	\$52.93	\$52.93
				Parts Cost	\$52.93

\$32.90 As per

Intrastats Cg 27.7.22

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent