

Service Repair Sheet SRS68245

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Katarina Hisinger

Company/ Hospital Name

Medival s.r.l

Department

Position

Direct Phone

+39 04977 5477

General Phone

Opera Account

00006557

Email

KHisinger@medival.it

Order Number

Date Received

04/Aug/2022

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Warranty

Notes 03/Aug/2022 Ryan Swaine

03/Aug/2022 Ryan Swaine

pn 0110051:553544, pn 0110081:689248, pn 0110081:689239, pn 0110081:689251, pn 0110057:636166. Failed sensors from various end users, to test and replace where appropriate.

04/Aug/2022 Robert Connor

Received 3 x UFO 130-2 s/n 689239, 689248, 689251, 1 x T-1 s/n 553544, appears to have leaked, 1 x T-7 s/n 636166

Ready For quote

CGreen 9.8.22.

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35159	Oxygen Sensor	0110081	689239	Yes
SRN35160	Oxygen Sensor	0110081	689248	Yes
SRN35161	Oxygen Sensor	0110081	689251	Yes
SRN35162	Oxygen Sensor	0110051	553544	N
SRN35163	Oxygen Sensor	0110057	636166	Yes

0140012 x 1 FOC - SRN 35162.
S/N, SRS, SRN.

0140013 x 1 ^{SRN 35163}
old S/N SRS, SRN
under warranty

0110051 x 1 € 37.75
SRS, SRN.

0140013 x 3
old S.

0140013 x 3 FOC
old S/N, SRS, SRN
under warranty



UPS Stand: 32x23x12x12cm or ship back with



Catherine Spence 15 Issues 10 Unread 11 ISO Tasks | H/W: CH EH JG ZT Future

Active Users 20.00 °C

v Search



Select Currency

Pounds| Euros| UsdRepair SRS68245 Values in Euros @ €1.17470: ~~£~~1.00

SRN35162	Oxygen Sensor	0110051			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0110051	1	€49.34	€49.34
				Parts Cost	€49.34

€ 37.75
As per
Intrastats

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent