

**M & A Malta**

CID10822 Opera CID10822 Type:Vandagraph Trade

M & A Malta Sir Luigi Preziosi Street, , Bugibba, , SPB2716, Malta

Tel GBP Trade Price List Vandagraph (0009) [Log Call](#)

Credit 30 Days after date of invoice Credit Limit 0.00GBP

VAT MT10373637

Account Home

Main Details

Account Memos

Sales History

Stock References

Customer Returns

Service Visits

Distributor Agreements

Documents Files

Linked Issues

Regulatory Agreements

SRS68200

SRS Created : 13 Jun 2022

Created By Ryan Swaine

[Print Barcodes](#)[Print A4 Sheet](#)[Split Items into Different SRS Numbers](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Handle with care

Add Items to Supplier Returns Box

[Add](#)

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

[Add Notes](#)

Service Repair Sheet 68200

Company / Hospital	M & A Malta
Contact Name	Shaun Upton
Department	
Position	
Company Phone	
Direct Phone	0035 621585065
Opera Account	CID10822
Email	shaun@mandamalta.com
Order Number	
Viamed ORD Number	
Date Received Into building	20 Jun 2022
Type	Quote Before Repair
Issues?	267877

Notes

13/Jun/2022 Ryan Swaine

13/Jun/2022 Ryan Swaine

TEK-OX sn. 2597. Not switching on

20/Jun/2022 Robert Connor

Received 1 x tek ox s/n TX 2597

22/Jun/2022 Catherine Spence

in engineers room waiting to be processed

08/Jul/2022 Catherine Spence

in engineers room waiting to be worked

19/Jul/2022 Catherine Spence

in engineers room

29/Jul/2022 Catherine Spence

In Engineers room waiting to be repaired

09/Aug/2022 Catherine Spence

in vandagraph room

LINKED ISSUE NOTES:

[267877:](#)

AutoGenerated Issue SRS68200 Appears to be Complete

02 Aug 2022 Catherine Spence

noted vandagraph order

Items for Repair

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN35098	Vandagraph Tek Ox	7910211	 1183078	TX2597	Oxygen Analyser Tek-Ox	No	No	Complete - Repaired	Not Switching On	00:30
SRN35098 Engineer Notes: INTERNAL NOTES not for customer discussion 02/Aug/2022 Michael Green The Tek-Ox Oxygen analyser has been repaired. The on/off button has been replaced.										

Currently Viewing ITEM SRN35098 Vandagraph Tek Ox 7910211 TX2597 Oxygen Analyser Tek-Ox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Tek-Ox Oxygen analyser has been repaired. The on/off button has been replaced.	02/Aug/2022 Michael Green The Tek-Ox Oxygen analyser has been repaired. The on/off button has been replaced.	The Tek-Ox Oxygen analyser has been repaired. The on/off button has been replaced.

2