

Service Repair Sheet SRS68244

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Kings College Hospital (us

00002990

invoices@kifm.onmicrosof

08/Aug/2022

Robert Connor

Viamed

Warranty

VIAMEDclean**Goods In Only**Decontamination
certificate provided
by customer ☒Cleaned by Viamed,
if no declaration certificate
from customer ☐Signed: _____
Date: _____**Goods Out Only**Cleaned by Viamed before
returning to customerSigned: _____
Date: _____

Notes 02/Aug/2022 Aqib Majeed

02/Aug/2022 Aqib Majeed

customer has max02me oxygen sensor (0111263), says the on/off button is not responding. still under warranty.

08/Aug/2022 Robert Connor

Received 1 x MAXO2ME s/n FJ31899021, with coiled cable 1608641, MAX-550E s/n FJ8999030, with flow diverter.

Ready For quote

Repair Complete Signed

CCNegan 9.8.22.

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35166	Oxygen Monitor	0111263	FJ31899021	Yes
SRN35167	Oxygen Monitor Cable	0131700	Tracking20	Yes
SRN35168	Oxygen Sensor	0110452	FJ8999030	Yes

} All part
of the
same unit
cg 9.8.22.

0140050 x 1 FOC

old S/N, SRS, SRN

To be replaced under warranty

0111263 x 1 FOC

New S/N, SRS, SRN

- includes cable and oxygen sensor.
(internal note only)

UPS x 1 FOC.

Service Repair Sheet 68244

Company/ Hospital Name

Opera Account

Email

Date Received

Booked in By

Kings College Hospital (use this one)

00002990

invoices@kifm.onmicrosoft.com

08/Aug/2022

Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35166	0111263	FJ31899021	Oxygen Monitor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0111263

Replaced with MAXO2 ME S/N GK17799001 which includes sensor GC41099175 and cable 1875422

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35167	0131700	Tracking20	Oxygen Monitor Cable	

No Fault Found

Time :0 Hour(s)

Replacement is included with the new MAXO2 ME

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35168	0110452	FJ8999030	Oxygen Sensor	

Time :0 Hour(s)

Replacement is included with the new MAXO2 ME
