

Not checked
through 09 10-8-22

Service Repair Sheet SRS68240

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Kyle Wilson

Company/ Hospital Name

Test and Measurement Aberdeen

Department

Position

Direct Phone

01467626100

General Phone

01467 626100

Opera Account

00012961

Email

kyle.wilson@vpplc.com

Order Number

744002221/1

Date Received

01/Aug/2022

Booked in By

Robert Connor

Main Company

Viamed

Type Return

~~Quote~~ Repair - P/O included
09 9-8-22

Notes 01/Aug/2022 Robert Connor

01/Aug/2022 Robert Connor

Received 1 x AX300 s/n 266541

Ready For quote

Repair Complete Signed

CGreen 11-8-22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35155	Oxygen Analyser	0111230	266541	N

0180028 x 1 @ £40

S/N, SRS, SRN

UPS x 1 @ £10.

**ESS**

Safety, Survey, Test & Measurement

Head Office: Hire Station Ltd, Fields Farm Road, Long Eaton, Nottingham, NG10 3FZ.
T: 0115 973 7400 E: lessc.apteam@vpplc.com

Test & Measurement Aberdeen
Test & Measurement Hire (ESS)
Unit C5 Kintore Business Park
Kintore
Aberdeenshire
AB51 0YQ
Tel: 01467 626100

SUNDRY ACCOUNT (ESS ONLY)
PURCHASE LEDGER
FIELDS FARM ROAD
LONG EATON
NOTTM
NG10 3FZ

Purchase Order

Order No : 744002221
Order date : 25/07/2022
Delivery date : 25/07/2022
Reference : 744009355
Our Ref : kywils
Page : 1 of 1

Account: P601500

Item	Description	Quantity	Price	Total
Please supply the following goods/services				
Purchase Order 744002221/1				
Please deliver to: Test & Measurement Aberdeen Test & Measurement Hire (ESS) Unit C5 Kintore Business Park Kintore Aberdeenshire AB51 0YQ				
Contact: kyle.wilson@vpplc.com 01467 626100				
PO.SPARIOS	Calibration of 1x Teledyne Oxygen Meter	1.00 Each	45.00 Each	45.00
PO.TRAN	PO Transport/Haulage	1.00 Each	10.00 Each	10.00

Total:

55.00

1. The above order number must be quoted on all delivery advice notes, invoices and other correspondence. Invoices omitting this number will be returned to the supplier.
 2. Our Terms and Conditions of Purchase of Goods and Services (as amended 1st August 2021) apply, a copy of which can be obtained from our Accounts Payable Dept.
 3. All invoices relating to this order should be invoiced to ESS, Fields Farm Road, Long Eaton, Nottingham, NG10 3FZ and submitted in single PDF format to Lessc.invoices@vpplc.com
- Any queries for accounts payable should be emailed to Lessc.apteam@vpplc.com

Service Repair Sheet 68240

Contact Name

Company/ Hospital Name

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Kyle Wilson

Test and Measurement Aberdeen

01467626100

01467 626100

00012961

kyle.wilson@vpplc.com

744002221/1

01/Aug/2022

Robert Connor

Repair

Ref

S/N

Equipment Type

SRN35155 0111230 266541

Oxygen Analyser

Calibrated

Time :0 Hour(s)

Parts Replaced

Qty: 1 0180028

A calibration test has been performed on the AX300 Oxygen analyser. A test certificate has been produced.
