

Service Repair Sheet SRS68259

Contact Name

Chris Kavanagh

Company/ Hospital Name

Just Inc Limited

Department

Position

Direct Phone

07738 828787

General Phone

Opera Account

CID14856

Email

chris@thinairsports.com

Order Number

Date Received

16/Aug/2022

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 11/Aug/2022 Kate Griffiths

11/Aug/2022 Kate Griffiths

Customer ordered 0014850 and has one that he is not getting a reading on
6020132264

SN: EGR10021 - I am unable to find these numbers and have asked customer to check but that is all he has
16/Aug/2022 Robert Connor

Received 1 x clip probe s/n EGR10021, box destroyed due to negligent packing by customer.

Ready For quote

Repair Complete Signed

CGNEON 19-8-22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35203	Pulse Oximetry Ear Clip Sensor	0014850	EGR10021	Yes

0040003 x 1 FOC
Old S/N, SRS, SRN

0014850 x 1 FOC
New S/N, SRS, SRN

UPS x 1 FOC.

Service Repair Sheet 68259

Contact Name

Company/ Hospital Name

Direct Phone

Opera Account

Email

Date Received

Booked in By

Chris Kavanagh

Just Inc Limited

07738 828787

CID14856

chris@thinairsports.com

16/Aug/2022

Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35203	0014850	EGR10021	Pulse Oximetry Ear Clip Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0014850

The pulse oximetry ear sensor has been replaced under warranty with SN:HAR10027.
