

Service Repair Sheet SRS68245

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return 01 Jan 2023

Katarina Hisinger

Medival s.r.l

+39 04977 5477

00006557

KHisinger@medival.it

04/Aug/2022

Robert Connor

Viamed

Warranty

Notes 03/Aug/2022 Ryan Swaine

03/Aug/2022 Ryan Swaine

pn 0110051:553544, pn 0110081:689248, pn 0110081:689239, pn 0110081:689251, pn 0110057:636166. Failed sensors from various end users, to test and replace where appropriate.

04/Aug/2022 Robert Connor

Received 3 x UFO 130-2 s/n 689239, 689248, 689251, 1 x T-1 s/n 553544, appears to have leaked, 1 x T-7 s/n 636166

Ready For quote

CGreen 9.8.22.

Repair Complete Signed

CGreen 19.8.22

€

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35159	Oxygen Sensor	0110081	689239	Yes
SRN35160	Oxygen Sensor	0110081	689248	Yes
SRN35161	Oxygen Sensor	0110081	689251	Yes
SRN35162	Oxygen Sensor	0110051	553544	N
SRN35163	Oxygen Sensor	0110057	636166	Yes

0140012 x 1 FOC - SRN 35162.
old S/N, SRS, SRN.

0110051 x 1 € 37.75
New SRS, SRN.

0140013 x 3 FOC
old S/N, SRS, SRN
under warranty

0110081 x 3 FOC
New S/N, SRS, SRN

UPS Stand: 32x23x12x12cm or ship back with

0140013 x 1 SRN 35163
old S/N SRS, SRN
under warranty

0110057 x 1 for
New S/N, SRS, SRN

Service Repair Sheet 68245

Contact Name	Katarina Hisinger
Company/ Hospital Name	Medival s.r.l
Direct Phone	+39 04977 5477
Opera Account	00006557
Email	KHisinger@medival.it
Date Received	04/Aug/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35159	0110081	689239	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced under warranty with S/N 823491

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35160	0110081	689248	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced under warranty with S/N 823500

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35161	0110081	689251	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081

Replaced under warranty with S/N 823501

Repair	Ref	S/N	Equipment Type	Complete - Repaired
SRN35162	0110051	553544	Oxygen Sensor	Time :0 Hour(s)

Parts Replaced

Qty: 1 0110051

The purchased replacement is S/N 563903

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35163	0110057	636166	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110057

Replaced under warranty with S/N 648562