

Service Repair Sheet SRS68216

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Sudath Weeraman

Prime Lanka Associates

Medical Engineering

Sales Manager

0094 10718732285

00007603

sudathweeraman@sltnet.lk

18/Aug/2022

Robert Connor

Viamed

Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 01/Jul/2022 Kate Griffiths

01/Jul/2022 Kate Griffiths

Sudath will return 2 x 0110429 - s/n: GL08399186 / GL08399225 as they are "defective". Under warranty

18/Aug/2022 Robert Connor

Received 3 x MAX-250E s/n GL08399186, GL08399225, GL08399232.

Ready For quote

Repair Complete Signed

CGNEEN 23.8.22.

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35207	Oxygen Sensor	0110429	GL08399186	Yes
SRN35208	Oxygen Sensor	0110429	GL08399225	Yes
SRN35209	Oxygen Sensor	0110429	GL08399232	Yes

0140013 x 3 FOC.

old S/N, SRS, SRN

0110429 x 3 FOC

new S/N, SRS, SRN

EXW.

Ship with next order.

32x 23x15x15cm 0.70kg



"Bringing quality to life."

No: 57/8, P.B. Alwis Perera Mawatha, Katubedda,
Moratuwa, Sri Lanka.

+94 071 873 2285 / +94 011 345 9456

011 262 4324

primelanka07@gmail.com
sudathweeraman17@gmail.com

02 August 2022

The Repair Team.

Viamed LTD, No.15, Station Road, Cross Hills, Keighley
West Yorkshire, BD20 7DT
United Kingdom.

Dear Sir,

The warranty replacement notice, for Oxygen sensor model MAX-250E
Please note below details for your reference.

Model – Oxygen Sensor MAX-250E

1. S/N - GL08399232
2. S/N - GL08399225
3. S/N - GL08399186

Return Reference No. SRS-68216

Thank you,

You're faithfully


S.J. Weeraman

Prime Lanka Associates
No.57/8, P.B.Alwis Perera Mawatha
Katubadda, Moratuwa
Sri Lanka.

Service Repair Sheet 68216

Contact Name	Sudath Weeraman
Company/ Hospital Name	Prime Lanka Associates
Department	Medical Engineering
Position	Sales Manager
Direct Phone	0094 10718732285
Opera Account	00007603
Email	sudathweeraman@sltnet.lk
Date Received	18/Aug/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35207	0110429	GL08399186	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110429

Replaced under warranty with S/N HA88499053

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35208	0110429	GL08399225	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110429

Replaced under warranty with S/N HA88499054

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35209	0110429	GL08399232	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110429

Replaced under warranty with S/N HA88499055
