

Service Repair Sheet SRS68219

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Magnus Persson

Company/ Hospital Name

Swevet - AB

Department

Position

Direct Phone

46 416 258 21

General Phone

46 771215500

Opera Account

00006308

Email

magnus.persson@swevet.se

Order Number

Date Received

20/Jul/2022

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

Notes 04/Jul/2022 Sophie Lines

04/Jul/2022 Sophie Lines

Returning at least 2x sensors which should be under warranty and 2x AX300s which don't work. I have asked him to provide the serial numbers

08/Jul/2022 Sophie Lines

Magnus has sent an email to say the sensors his customer thought were faulty were not screwed in correctly, and are now working fine.

I have asked him if he is still returning the 2x AX300 s he mentioned - awaiting reply

08/Jul/2022 Sophie Lines

Magnus has confirmed the AX300 s have been sent for repair but he does not know the serial numbers

20/Jul/2022 Robert Connor

Received 2 x AX300 s/n 328346, with base and 2 suction feet, 328348, with complete base, 2 x 0131202 s/n 0013869, 0014048, 2 x R17MED s/n 722371, 491492, with 2 x flow diverter.

Ready For quote

CGNEON 5.8.22

€

Repair Complete Signed

CGNEON 23.8.22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35138	Oxygen Analyser	0111230	328346	2
SRN35139	Oxygen Analyser	0111230	328348	2
SRN35140	Oxygen Monitor Cable	0131202	0013869	2
SRN35141	Oxygen Monitor Cable	0131202	0014048	2
SRN35142	Oxygen Sensor	0110017	491492	2
SRN35143	Oxygen Sensor	0110017	722371	2

Sold Aug 2020
 no record in System
 at date code.
 Pre 2011 pot.
 checked with derel
 cg 5.8.22

0140004 x 2 FOC. no fault found.

S/N's, SRS, SRN's.

0140025 x 2 FOC NO fault found
 S/N's, SRS, SRN's.

0140012 x 2 FOC faulty.

old S/N's, SRS, SRN's

0110017 x 2

new S/N's

€32.00 each.

Amend cg 23.8.22

Please add
 insurance on.
 cg 5.8.22.

Service Repair Sheet 68219

Contact Name	Magnus Persson
Company/ Hospital Name	Swevet - AB
Direct Phone	46 416 258 21
General Phone	46 771215500
Opera Account	00006308
Email	magnus.persson@swevet.se
Order Number	SRS68219
Date Received	20/Jul/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN35138	0111230	328346	Oxygen Analyser	No Fault Found Time :0 Hour(s)

The monitor is no fault found

Repair	Ref	S/N	Equipment Type	
SRN35139	0111230	328348	Oxygen Analyser	No Fault Found Time :0 Hour(s)

The monitor is no fault found

Repair	Ref	S/N	Equipment Type	
SRN35140	0131202	0013869	Oxygen Monitor Cable	No Fault Found Time :0 Hour(s)

The monitor cable is no fault found

Repair	Ref	S/N	Equipment Type	
SRN35141	0131202	0014048	Oxygen Monitor Cable	No Fault Found Time :0 Hour(s)

The monitor cable is no fault found

Repair	Ref	S/N	Equipment Type	
SRN35142	0110017	491492	Oxygen Sensor	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017

Replaced with S/N 773863

Service Repair Sheet 68219

Contact Name

Magnus Persson

Company/ Hospital Name

Swevet - AB

Direct Phone

46 416 258 21

General Phone

46 771215500

Opera Account

00006308

Email

magnus.persson@swevet.se

Order Number

SRS68219

Date Received

20/Jul/2022

Booked in By

Robert Connor

Repair

Ref

S/N

Equipment Type

SRN35143

0110017

722371

Oxygen Sensor

Complete - Repaired

Time :0 Hour(s)

Parts Replaced

Qty: 1

0110017

Replaced with S/N 773864
