

Service Repair Sheet SRS68257

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Grye Belza
Pilgrim Hospital
Clinical Engineering
Trainee Medical Engineering Tech
01205 445205
01205 364801
00000600
grye.belza@ulh.nhs.uk

31/Aug/2022
Robert Connor
Viamed
Warranty

VIAMEDclean	
Goods In Only	
Decontamination certificate provided by customer	<input type="checkbox"/>
Cleaned by Viamed if no declaration certificate from customer	<input type="checkbox"/>
Signed: _____	
Date: _____	
Goods Out Only	
Cleaned by Viamed before returning to customer	
Signed: _____	
Date: _____	

Notes 10/Aug/2022 Steve Hardaker

10/Aug/2022 Steve Hardaker

Returning an R-22MED 0110022 s/n 618876 D1, sold 8th Oct 21, still under warranty. Low output, measured at 0.08mV.

As they are using them in an Atom incubator, I suggested they may want to move over to the R-22VA 0110039. If the returns paperwork asks to replace this sensor with an R-22VA, we should be able to do it as they are the same price.

31/Aug/2022 Robert Connor

Received 1 x R22med S/N 618876

Ready For quote

Repair Complete Signed

CG. Connor 1-9-22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35439	Oxygen Sensor	0110022	618876	Yes

0140013 x 1 @ FOC
old S/N, SRS, SRN

0110022 x 1 @ FOC
new S/N, SRS, SRN

UPS x 1 @ £0

Service Repair Sheet 68257

Contact Name	Grye Belza
Company/ Hospital Name	Pilgrim Hospital
Department	Clinical Engineering
Position	Trainee Medical Engineering Technician
Direct Phone	01205 445205
General Phone	01205 364801
Opera Account	00000600
Email	grye.belza@ulh.nhs.uk
Date Received	31/Aug/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35439	0110022	618876	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110022

Replaced under warranty with S/N 814914
