

Invoice Correction 5261191052

ORIGINAL

Invoice Correction Date: 06.09.2022

Honeywell Healthcare Solutions GmbH

Alter Holzhafen 18

Purchase Order No: RTS3100882

23966 Wismar

Germany

Bill to: 1797448

Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom

Sold to: 1797448

Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom

Order Information:

Credit Memo Request: 63939469
Sales Office: 2170 DE SPS Wismar
Incoterms: FCA Origin
Payment Terms: Net 30 Days After Invoice Date

Ship to: 1797448

Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom

ITEM NO.	Material No.	QTY	UOM	UNIT PRICE	EXT. PRICE	VAT %
000010	E1002734 Oxygen Sensor OOD103 VAN 8010008 Customer Part Nbr: 8010008 credit note for SN:111228	1 ✓	EA	40,00 <i>Should be 19.41</i>	-40,00	0%
000020	E1001721 Oxygen Sensor OOD103-2V Customer Part Nbr: 8010004 credit note for SN: 133591; 135105	2 ✓	EA	44,44 <i>Should be 20.00 and 26.73</i>	-88,88	0%

Totals

Total Before VAT -128,88 EUR
VAT-Total 0,00 EUR
Total Amount -128,88 EUR

Tax Information

Tax Exempt Reason: Tax free export - Goods
Fulfilment Date: 06.09.2022

Duns #:

Bank Details: No Payment Due

Account Name:

Account No:

Bank Key:

Swift Code:

IBAN:

Payment method:

Registered No: Schwerin HRB 1838

VAT Reg No: DE137437213

Federal ID #:

Registered Address: Honeywell Healthcare Solutions GmbH, Alter Holzhafen 18, Wismar, 23966, Germany

Credit Analyst: Xenia Musat

Sales Rep: Stefan Dreyer

Customer Care Rep: Jessica Wagner +49 3841 360 206

Honeywell Healthcare Solutions GmbH

WEEE Reg.No.: 57798680

Internet: www.envitec.com

Managing Director: Marcus Ostländer

email: info@envitec.com

Delivery exclusive to our General Terms (February 2016). We retain title to our goods and deliveries until all the payment from the sales contract have been received. Your order will be executed exclusively to our terms and conditions. These can be sent by separate request or viewed at www.envitec.com

Remittance Email: HoneywellEMEARemits@Honeywell.com

PRÜFBERICHT – TEST REPORT

Sauerstoffsensoren/Oxygen Sensors OOA, OOI, OOD


ENVITEC
by Honeywell

Kunde/ Customer	Vanda graph	Retour/ RMA- No.	Kunde/Customer	RTS 3100882	EnviteC	300 255352
Artikel/ Article	00D103, 00D103 2V	Anzahl/ Quantity	1, 2	Eing.Datum/ Inc.Date	29.09.22	
Bearbeitet/ processed	V. Buer	Prüfdatum/ Insp. Date	02.09.22	Geprüft/ Inspected	Buer	

Produkt/ Identification			Messwert/ Test Result				Bewertung/ Evaluation			
Nr.	Seriennummer/ Serial no.	Lieferlos/ Manufad. code	Luftwert/ Air signal @ 20,9% O ₂ [mV]	Nullsignal/ Offset @ 0% O ₂ [µV]	Linearität/ Linearity [%]	Bemerkung/ Remark	außerhalb Garantie/ out of warranty	kein Fehler festgestellt/ no failure found	Fehlerkode/ Failure- code	Austausch / Replacement
1	111 228	05122	0						04	
2	133 591	08121	0						04	
3	135 105	11121	7.4	51	1.2				01	
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										
17										
18										
19										
20										

Fehler O2-S002: Signal instabil / Signal not stable

Fehler O2-S001: Luftwert außerhalb Toleranz/ Air signal out of tolerance
 Fehler O2-S003: Offset außerhalb Toleranz/ Offset out of tolerance
 Fehler O2-S005: Gehäuse defekt/ Housing defective
 Fehler O2-S007: Sonstiges (unter Angabe in Bemerkung) / Others (see remark)
 Fehler O2-S002: Signal instabil / Signal not stable
 Fehler O2-S004: Signal 0mV / Signal 0mV
 Fehler O2-S006: Elektrolyt Austritt / Electrolyte leakage



Honeywell Healthcare Solutions GmbH

✓CID4348 Opera 00007282 Type:Company Supplier Customer
Honeywell Healthcare Solutions GmbH Alter Holzhafen 18, Wismar...
D-23966, Germany
Tel 0049 3841 360204 Euro Distributor (0004) Log Call
VAT DE137437213

- Account Home
 Main Details
 Account Memos
 Sales History
 Purchase Orders
 Supplier Returns
 Stock References
 Cust./Supp. Returns
 Service Visits
- Distributor Agreements
 Documents Files
 Linked Issues
 Regulatory Agreements

BOX:882

Manufacturer RMA : 300255352

☒ Repaired ☐ No Fault Found

 Returned Barcode

 Close File 882

 Tick All Replaced

Stock Ref	Sup Ref	B/C	S/N	Fault	Replaced	No Fault Found	Repaired	Credited	Out Warranty	Returned Unrepaired	Notes
8010004		1835827	JJ133591	No Output Country of Origin: Germany Customs Value: 5.00 euro	☐	☐	☐	☒	☐	☐	
8010004		1898599	JJ135105	Low Output Country of Origin: Germany Customs Value: 5.00 euro	☐	☐	☐	☒	☐	☐	
8010008		2005138	M01111228	No Output Country of Origin: Germany Customs Value: 5.00 euro	☐	☐	☐	☒	☐	☐	

 Update Returns