



Duikshop Galicia

 CID4225 Opera **GALICIA** Type: **Vandagraph Trade**

Duikshop Galicia Liersesteenweg 76, Aarschot, , B-3200, Belgium

Tel 0032 475 25 77 20 GBP Trade Price List Vandagraph (0009)

Credit 30 Days after date of invoice Credit Limit 0.00GBP

VAT BE0841891209



 Account Home

 Main Details

Account Memos

 Sales History

Stock References

 Cust./Supp. Returns

Service Visits

Distributor Agreements

Documents
Files

 **Linked
Issues**

Regulatory Agreements

Agreed to try UPS again - RS 05/05/22

SRS68261

SRS Created : 15 Aug 2022

Created By Ryan Swaine

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock

Unopened - will apply to all items on srs

- ☐ Clear From System - Force from System.
 - will apply to all items on srs

Add notes to SRS

Add Notes

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Add

☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs

☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68261		Notes
Company / Hospital	Duikshop Galicia	15/Aug/2022 Ryan Swaine
Contact Name	Steven Galicia	15/Aug/2022 Ryan Swaine
Department		2x TEK-OX not turning on, sn 3216, 1495
Position		18/Aug/2022 Robert Connor
Company Phone	0032 475 25 77 20	Received 2 x tek-ox s/n 1495, partly disassembled, batteries appear to have leaked slightly, 3216, also partly disassembled.
Direct Phone	0032 475257720	06/Sep/2022 Catherine Spence
Opera Account	GALICIA	engineers room
Email	steven@galicia.be	LINKED ISSUE NOTES:
Order Number		272357 :
Viamed ORD Number		AutoGenerated Issue SRS68261 Appears to be Complete
Date Received Into building	18 Aug 2022	272358 :
Type	Quote Before Repair	AutoGenerated Issue SRS68261 Appears to be Complete
Issues?	272357 272358	

Items for Repair

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN35205	Vandagraph Tek Ox	7910211	 633042	TX1495	Oxygen Analyser Tek-Ox	No	No	Complete - Repaired 20 Sep 2022 Michael Green	Battery Leak	01:00
SRN35205 Engineer Notes: INTERNAL NOTES not for customer discussion 02/Sep/2022 Michael Green The Tek-Ox analyser has been tested. The unit has had a battery leak. The PCB still powers up. There are signs of corrosion within the wiring loom. The battery door contact needs to be replaced. 20/Sep/2022 Michael Green The Tek-Ox analyser has been repaired. The wiring loom and battery door contacts have been replaced.										
SRN35206	Vandagraph Tek Ox	7910201	 1663092	TX3216	Oxygen Analyser Tek-Ox + Quick-Ox	Yes	No	No Fault Found 20 Sep 2022 Michael Green	No Fault Found	00:00
SRN35206 Engineer Notes: INTERNAL NOTES not for customer discussion 02/Sep/2022 Michael Green The Tek-Ox analyser has been tested. The unit appears to work as expected. A longer test will be performed. 20/Sep/2022 Michael Green The Tek-Ox analyser has been tested. No fault was found.										

Currently Viewing ITEM SRN35205 Vandagraph Tek Ox 7910201 TX3216 Oxygen Analyser Tek-Ox + Quick-Ox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Tek-Ox analyser has been tested. No fault was found. The batteries have been replaced.	02/Sep/2022 Michael Green The Tek-Ox analyser has been tested. The unit appears to work as expected. A longer test will be performed. 20/Sep/2022 Michael Green The Tek-Ox analyser has been tested. No fault was found.	The Tek-Ox analyser has been tested. No fault was found. The batteries have been replaced.