

# Service Repair Sheet SRS68225

Contact Name  
Company/ Hospital Name  
Department  
Position  
Direct Phone  
General Phone  
Opera Account  
Email  
Order Number  
Date Received  
Booked in By  
Main Company  
Type Return

Paul Derman  
Southmead Hospital  
Clinical Engineering

0117 4146069  
0117 9505050  
00000740  
paul.derman@nbt.nhs.uk

10/Aug/2022  
Robert Connor  
Viamed  
Warranty

## VIAMEDclean

**Goods In Only**  
Decontamination  
certificate provided  
by customer ☐

Cleaned by Viamed,  
if no declaration certificate  
from customer ☒

Signed: RC  
Date: 10/8/22

## Goods Out Only

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_  
Date: \_\_\_\_\_

Notes 08/Jul/2022 Steve Hardaker

08/Jul/2022 Steve Hardaker

He reported a MaxO2 ME Serial no. GK17799012 that is not alarming, it appears to be just the sounder as the display does indicate an alarm condition.

When he demonstrated this on the phone, it briefly worked and then stopped.

Repair/replace under warranty.

10/Aug/2022 Robert Connor

Received 1 x MAXO2ME s/n GK17799021, with cable ID 1875418, MAX550E s/n GK56999060, and blue tee.

Ready For quote

careen 27.9.22

Repair Complete Signed

careen 27.9.22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35180	Oxygen Monitor	0111263	GK17799021	Yes
SRN35181	Oxygen Monitor Cable	0131700	Tracking6	
SRN35182	Oxygen Sensor	0110452	GK56999060	

3 Part of unit

0140050 x 1 @ £0.  
old SIN, SRN, SRS.

0111263 x 1 @ £0  
new SIN, SRS, SRN

UPS x 1 @ £0.



Returns Department – Returns No. SRS68225  
F.A.O. Steve Hardaker  
Viamed Ltd  
15 Station Road  
Cross Hills  
Keighley  
West Yorkshire  
BD20 7DT

No

08/08/2021

Dear Steve,

Please see enclosed O2 monitor S/No. GK17799021 as per our telephone conversation. The monitor has a defective sounder.

Many Thanks,

*Paul.*

Anaesthetic Service Head – Deputy Head of Dept. & MDSO  
Clinical Equipment Services, Gate 10 Level 6  
North Bristol NHS Trust, Southmead Hospital, Westbury on Trym, Bristol, BS10 5NB. Tel 0117 4146069

Service Repair Sheet 68225

Contact Name	Paul Derman
Company/ Hospital Name	Southmead Hospital
Department	Clinical Engineering
Direct Phone	0117 4146069
General Phone	0117 9505050
Opera Account	00000740
Email	paul.derman@nbt.nhs.uk
Date Received	10/Aug/2022
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35180	0111263	GK17799021	Oxygen Monitor	
				Time :0 Hour(s)

The MAXO2ME Oxygen monitor has been replaced under warranty with SN:HG36099001.

---

Repair	Ref	S/N	Equipment Type	
SRN35181	0131700	Tracking6	Oxygen Monitor Cable	
				Time :0 Hour(s)

The sensor cable has been replaced under warranty.

---

Repair	Ref	S/N	Equipment Type	
SRN35182	0110452	GK56999060	Oxygen Sensor	
				Time :0 Hour(s)

The Oxygen sensor has been replaced under warranty.

---