## Viamed Returns Shipping Invoice

Delivery Address: Date: 24 Dec 2024 Shipper Address:

Teledyne Analytical Instruments RMA: Viamed

16830 Chestnut Street

City Of Industry

Cynar Magno Viamed RN: RTS11001013 15 Station Road

Cross Hills Keighley

California West Yorkshire

91748-1020 BD20 7DT 0016269341589 +44 (0) 153

+44 (0) 1535 634542 +44 (0) 1535 635582 info@viamed.co.uk

Returns Under Warranty Value for Customs: \$312 See Attached Listing for Serial numbers and Faults

Part Number	P/N / Value	Description	Quantity		
C44611-R22A	0110122 (\$20.00)	Automotive Oxygen Sensor R-22A	3		
	Tariff Code: HTS Code 9	027.10.2000			
	Country of Origin: USA				
C44611-R22AHJR	0110361 (\$27.00)	Oxygen sensor R-22AHJR Jikco	8		
	Tariff Code: HTS Code 9	027.10.2000			
	Country of Origin: USA				
C44611-R22AV	0110132 (\$18.00)	Automotive Oxygen Sensor R-22A	2		
	Tariff Code: HTS Code 9027.10.2000				
	Country of Origin: USA				

Part Number	Serial Number	RMA	Fault Description
C44611-R22A	192998		Fail 32.7mV reading High. Failed in QA did not reach end user
C44611-R22A	210467		Output ( 7mV - 13mV ) 13.6 Failed in Q.A. Did not reach end user
C44611-R22A	210494		Output (7mV - 13mV) 13.9 Failed in Q.A. Did not reach end user
C44611-R22AV	212235		Output ( 9mV - 13mV ) 14.2 Failed in Q.A. Did not reach end user
C44611-R22AV	212299		Output ( 9mV - 13mV ) 14.2 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A212736		Output ( 10.5 - 13.5 mV ) 10.4 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A212748		Output (10.5 - 13.5 mV) High 32.7mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A212765		Output ( 10.5 - 13.5 mV ) 9.6mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A212771		Output ( 10.5 - 13.5 mV ) 10.2 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A212779		Output ( 10.5 - 13.5 mV ) 10.3 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A212800		Output ( 10.5 - 13.5 mV ) 10.0 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A212811		Output ( 10.5 - 13.5 mV ) 10.4 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A212818		Output ( 10.5 - 13.5 mV ) 10.2. mV Failed in Q.A. Did not reach end user