

# Viamed Returns Shipping Invoice

Delivery Address:  
Teledyne Analytical Instruments  
Cynar Magno  
16830 Chestnut Street  
City Of Industry  
California  
91748-1020  
0016269341589

Date: 19 Sep 2025  
RMA:  
Viamed RN: RTS11001034

Shipper Address:  
Viamed  
15 Station Road  
Cross Hills  
Keighley  
West Yorkshire  
BD20 7DT  
+44 (0) 1535 634542  
+44 (0) 1535 635582  
info@viamed.co.uk

---

Part Number	P/N / Value	Description	Quantity
C44611-R22A	0110122 (\$20.00)	Automotive Oxygen Sensor R-22A	5
	Tariff Code: HTS Code 9027.10.2000		
	Country of Origin: USA		
C44611-R22AH	0110142	Automotive Oxygen Sensor R-22A	3
	Tariff Code: HTS Code 9027.10.2000		
	Country of Origin: Mexico		

Part Number	Serial Number	RMA	Fault Description
C44611-R22A	263332		Output ( 7mV - 13mV ) difficult to get on tester.ok once on. Failed in Q.A. Did not reach end user
C44611-R22A	263368		Output ( 7mV - 13mV ) 14.0 n Move Item to location 126552 n Failed in Q.A. Did not reach end user
C44611-R22A	263907		Output ( 7mV - 13mV ) 13.5 mV Failed in Q.A. Did not reach end user
C44611-R22A	263920		Output ( 7mV - 13mV ) 13.8 mV Failed in Q.A. Did not reach end user
C44611-R22A	263945		Output ( 7mV - 13mV ) 14.1 mV Failed in Q.A. Did not reach end user
C44611-R22AH	257947		Output ( 10.5mV - 13.5mV ) 15.2 mV Failed in Q.A. Did not reach end user
C44611-R22AH	260123		Output ( 10.5mV - 13.5mV )14.5 mV Failed in Q.A. Did not reach end user
C44611-R22AH	260127		Output ( 10.5mV - 13.5mV ) 13.8 mV Failed in Q.A. Did not reach end user