

Viamed Returns Shipping Invoice

Delivery Address:
Teledyne Analytical Instruments
Warranty Returns
16830 Chestnut Street
City Of Industry
California
91748-1020
0016269341589

Date: 14 Mar 2026
RMA:
Viamed RN: RTS11001065

Shipper Address:
Viamed
15 Station Road
Cross Hills
Keighley
West Yorkshire
BD20 7DT
+44 (0) 1535 634542
+44 (0) 1535 635582
info@viamed.co.uk

Part Number	P/N / Value	Description	Quantity
C43690-R17A	0110117 (\$27.00) Tariff Code: HTS Code 9027.10.2000 Country of Origin: USA	Automotive Oxygen Sensor R-17A	90

Part Number	Serial Number	RMA	Fault Description
C43690-R17A	179101		Old Date Code As discussed and arranged with Rob Milversted 90 x C43690-R17A oxygen sensors are being returned for replacement due to old manufactured dates. These sensors are not sellable as they will not be acceptable to customers. The stock at Teledyne has not been rotated and these sensors could have been supplied months ago, instead of being delayed for so long.
C43690-R17A	179102		Old Date Code As discussed and arranged with Rob Milversted 90 x C43690-R17A oxygen sensors are being returned for replacement due to old manufactured dates. These sensors are not sellable as they will not be acceptable to customers. The stock at Teledyne has not been rotated and these sensors could have been supplied months ago, instead of being delayed for so long.
C43690-R17A	179103		Old Date Code As discussed and arranged with Rob Milversted 90 x C43690-R17A oxygen sensors are being returned for replacement due to old manufactured dates. These sensors are not sellable as they will not be acceptable to customers. The stock at Teledyne has not been rotated and these sensors could have been supplied months ago, instead of being delayed for so long.
C43690-R17A	179104		Old Date Code As discussed and arranged with Rob Milversted 90 x C43690-R17A oxygen sensors are being returned for replacement due to old manufactured dates. These sensors are not sellable as they will not be acceptable to customers. The stock at Teledyne has not been rotated and these sensors could have been supplied months ago, instead of being delayed for so long.
C43690-R17A	179105		Old Date Code As discussed and arranged with Rob Milversted 90 x C43690-R17A oxygen sensors are being returned for replacement due to old manufactured dates. These sensors are not sellable as they will not be acceptable to customers. The stock at Teledyne has not been rotated and these sensors could have been supplied months ago, instead of being delayed for so long.
C43690-R17A	179106		Old Date Code As discussed and arranged with Rob Milversted 90 x C43690-R17A oxygen sensors are being returned for replacement due to old manufactured dates. These sensors are not sellable as they will not be acceptable to customers. The stock at Teledyne has not been rotated and these sensors could have been supplied months ago, instead of being delayed for so long.
C43690-R17A	179107		Old Date Code As discussed and arranged with Rob Milversted 90 x C43690-R17A oxygen sensors are being returned for replacement due to old manufactured dates. These sensors are not sellable as they will not be acceptable to customers. The stock at Teledyne has not been rotated and these sensors could have been supplied months ago, instead of being delayed for so long.
C43690-R17A	179108		Old Date Code As discussed and arranged with Rob Milversted 90 x C43690-R17A oxygen sensors are being returned for replacement due to old manufactured dates. These sensors are not sellable as they will not be acceptable to customers. The stock at Teledyne has not been rotated and these sensors could have been supplied months ago, instead of being delayed for so long.
C43690-R17A	179109		Old Date Code As discussed and arranged with Rob Milversted 90 x C43690-R17A oxygen sensors are being returned for replacement due to old manufactured dates. These sensors are not sellable as they will not be acceptable to customers. The stock at Teledyne has not been rotated and these sensors could have been supplied months ago, instead of being delayed for so long.
C43690-R17A	179110		Old Date Code As discussed and arranged with Rob Milversted 90 x C43690-R17A oxygen sensors are being returned for replacement due to old manufactured dates. These sensors are not sellable as they will not be acceptable to customers. The stock at Teledyne has not been rotated and these sensors could have been supplied months ago, instead of being delayed for so long.

Part Number	Serial Number	RMA	Fault Description
C43690-R17A	179188		Old Date Code As discussed and arranged with Rob Milversted 90 x C43690-R17A oxygen sensors are being returned for replacement due to old manufactured dates. These sensors are not sellable as they will not be acceptable to customers. The stock at Teledyne has not been rotated and these sensors could have been supplied months ago, instead of being delayed for so long.
C43690-R17A	179189		Old Date Code As discussed and arranged with Rob Milversted 90 x C43690-R17A oxygen sensors are being returned for replacement due to old manufactured dates. These sensors are not sellable as they will not be acceptable to customers. The stock at Teledyne has not been rotated and these sensors could have been supplied months ago, instead of being delayed for so long.
C43690-R17A	179190		Old Date Code As discussed and arranged with Rob Milversted 90 x C43690-R17A oxygen sensors are being returned for replacement due to old manufactured dates. These sensors are not sellable as they will not be acceptable to customers. The stock at Teledyne has not been rotated and these sensors could have been supplied months ago, instead of being delayed for so long.

Part Number	Serial No.	RMA	Fault Report
C43690-R17A	179101		
C43690-R17A	179102		
C43690-R17A	179103		
C43690-R17A	179104		
C43690-R17A	179105		
C43690-R17A	179106		
C43690-R17A	179107		
C43690-R17A	179108		
C43690-R17A	179109		
C43690-R17A	179110		
C43690-R17A	179111		
C43690-R17A	179112		
C43690-R17A	179113		
C43690-R17A	179114		
C43690-R17A	179115		
C43690-R17A	179116		
C43690-R17A	179117		
C43690-R17A	179118		
C43690-R17A	179119		
C43690-R17A	179120		
C43690-R17A	179121		
C43690-R17A	179122		
C43690-R17A	179123		
C43690-R17A	179124		
C43690-R17A	179125		
C43690-R17A	179126		
C43690-R17A	179127		
C43690-R17A	179128		
C43690-R17A	179129		
C43690-R17A	179130		
C43690-R17A	179131		
C43690-R17A	179132		
C43690-R17A	179133		
C43690-R17A	179134		

Part Number	Serial No.	RMA	Fault Report
C43690-R17A	179135		
C43690-R17A	179136		
C43690-R17A	179137		
C43690-R17A	179138		
C43690-R17A	179139		
C43690-R17A	179140		
C43690-R17A	179141		
C43690-R17A	179142		
C43690-R17A	179143		
C43690-R17A	179144		
C43690-R17A	179145		
C43690-R17A	179146		
C43690-R17A	179147		
C43690-R17A	179148		
C43690-R17A	179149		
C43690-R17A	179150		
C43690-R17A	179151		
C43690-R17A	179152		
C43690-R17A	179153		
C43690-R17A	179154		
C43690-R17A	179155		
C43690-R17A	179156		
C43690-R17A	179157		
C43690-R17A	179158		
C43690-R17A	179159		
C43690-R17A	179160		
C43690-R17A	179161		
C43690-R17A	179162		
C43690-R17A	179163		
C43690-R17A	179164		
C43690-R17A	179165		
C43690-R17A	179166		
C43690-R17A	179167		
C43690-R17A	179168		

Part Number	Serial No.	RMA	Fault Report
C43690-R17A	179169		
C43690-R17A	179170		
C43690-R17A	179171		
C43690-R17A	179172		
C43690-R17A	179173		
C43690-R17A	179174		
C43690-R17A	179175		
C43690-R17A	179176		
C43690-R17A	179177		
C43690-R17A	179178		
C43690-R17A	179179		
C43690-R17A	179180		
C43690-R17A	179181		
C43690-R17A	179182		
C43690-R17A	179183		
C43690-R17A	179184		
C43690-R17A	179185		
C43690-R17A	179186		
C43690-R17A	179187		
C43690-R17A	179188		
C43690-R17A	179189		
C43690-R17A	179190		