

Viamed Returns Shipping Invoice

Delivery Address:
Teledyne Analytical Instruments
Warranty Returns
16830 Chestnut Street
City Of Industry
California
91748-1020
0016269341589

Date: 01 Sep 2026
RMA:
Viamed RN: RTS11001097

Shipper Address:
Viamed
15 Station Road
Cross Hills
Keighley
West Yorkshire
BD20 7DT
+44 (0) 1535 634542
+44 (0) 1535 635582
info@viamed.co.uk

Returns Under Warranty Value for Customs : \$
See Attached Listing for Serial numbers and Faults

Part Number	P/N / Value	Description	Quantity
C43690-R17AV	0110127 (\$26.00 each) Tariff Code: HTS Code 9027.10.2000 Country of Origin: USA	Automotive Oxygen Sensor R-17A	4
C44611-R22AHJR	0110361 (\$20.00 ea) Tariff Code: HTS Code 9027.10.2000 Country of Origin: USA	Oxygen sensor R-22AHJR Jikco	14

Part Number	Serial Number	RMA	Fault Description
C43690-R17AV	340436		Output (9mV - 13mV) 14.1 mV Failed in Q.A. Did not reach end user
C43690-R17AV	340442		Output (9mV - 13mV) 13.9 mV Failed in Q.A. Did not reach end user
C43690-R17AV	340444		Output (9mV - 13mV) 14.3 mV Failed in Q.A. Did not reach end user
C43690-R17AV	340445		Output (9mV - 13mV) 14.7mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A377506		Output (10.5 - 13.5 mV) 10.2 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A377507		Output (10.5 - 13.5 mV) 10.4 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A377512		Output (10.5 - 13.5 mV) 10.1 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A377515		Output (10.5 - 13.5 mV) 10.3 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A377516		Output (10.5 - 13.5 mV) 10.2 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A382816		Output (10.5 - 13.5 mV) 10.3 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A382827		Output (10.5 - 13.5 mV) 10.3 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A382830		Output (10.5 - 13.5 mV) 9.8 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A382841		Output (10.5 - 13.5 mV) 10.2 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A382842		Output (10.5 - 13.5 mV) 10.1 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A382844		Output (10.5 - 13.5 mV) 9.7 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A382847		Output (10.5 - 13.5 mV) 10.4 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A382854		Output (10.5 - 13.5 mV) 10.3 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A382877		Output (10.5 - 13.5 mV) 10.1 mV Failed in Q.A. Did not reach end user

Part Number	Serial No.	RMA	Fault Report
C43690-R17AV	340436		
C43690-R17AV	340442		
C43690-R17AV	340444		
C43690-R17AV	340445		
C44611-R22AHJR	A377506		
C44611-R22AHJR	A377507		
C44611-R22AHJR	A377512		
C44611-R22AHJR	A377515		
C44611-R22AHJR	A377516		
C44611-R22AHJR	A382816		
C44611-R22AHJR	A382827		
C44611-R22AHJR	A382830		
C44611-R22AHJR	A382841		
C44611-R22AHJR	A382842		
C44611-R22AHJR	A382844		
C44611-R22AHJR	A382847		
C44611-R22AHJR	A382854		
C44611-R22AHJR	A382877		