

# Viamed Returns Shipping Invoice

Delivery Address:  
Teledyne Analytical Instruments  
Margie Read  
16830 Chestnut Street  
City Of Industry  
California  
91748-1020

Date: 27 May 2025  
RMA:  
Viamed RN: RTS1100903

Shipper Address:  
Viamed  
15 Station Road  
Cross Hills  
Keighley  
West Yorkshire  
BD20 7DT  
+44 (0) 1535 634542  
+44 (0) 1535 635582  
info@viamed.co.uk

---

Returns Under Warranty Value for Customs : \$100.00

See Attached Listing for Serial numbers and Faults

---

Part Number	P/N / Value	Description	Quantity
C44611-R22AHJR	0110361 (\$27.00)	Oxygen sensor R-22AHJR Jikco	12
	Tariff Code: HTS Code 9027.10.2000		
	Country of Origin: USA		

Part Number	Serial Number	RMA	Fault Description
C44611-R22AHJR	A838689		Output ( 10.5 - 13.5 mV ) 14.2mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A868064		Output ( 10.5 - 13.5 mV ) 14.9 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A868067		Output ( 10.5 - 13.5 mV ) 14.2mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A868074		output 14.2 mV fail QA Fail Failed in Q.A. Did not reach end user
C44611-R22AHJR	A868077		Output ( 10.5 - 13.5 mV ) 14.9 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A868082		Output ( 10.5 - 13.5 mV ) 14.6 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A868099		Output ( 10.5 - 13.5 mV ) 14.9 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A868119		Output ( 10.5 - 13.5 mV ) 14.2 mVFailed in Q.A. Did not reach end user
C44611-R22AHJR	A868125		Output ( 10.5 - 13.5 mV ) 14.1 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A868126		Output ( 10.5 - 13.5 mV ) 14.1 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A868139		Output ( 10.5 - 13.5 mV ) 14.2 mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A868174		Output ( 10.5 - 13.5 mV ) 14.2 mV Failed in Q.A. Did not reach end user