

# Viamed Returns Shipping Invoice

Delivery Address:  
Teledyne Analytical Instruments  
Margie Read  
16830 Chestnut Street  
City Of Industry  
California  
91748-1017  
0016269341589

Date: 17 Jan 2024  
RMA: 0058544  
Viamed RN: RTS1100919

Shipper Address:  
Viamed  
15 Station Road  
Cross Hills  
Keighley  
West Yorkshire  
BD20 7DT  
+44 (0) 1535 634542  
+44 (0) 1535 635582  
info@viamed.co.uk

---

Returns Under Warranty Value for Customs : \$162  
See Attached Listing for Serial numbers and Faults

---

Part Number	P/N / Value	Description	Quantity
C44611-R22AV	0110132 (\$18.00)	Automotive Oxygen Sensor R-22A	9
	Tariff Code: HTS Code 9027.10.2000		
	Country of Origin: USA		

Part Number	Serial Number	RMA	Fault Description
C44611-R22AV	947060	0058544	Output ( 9mV - 13mV ) 8.8 Failed in Q.A. Did not reach end user
C44611-R22AV	947085	0058544	Output ( 9mV - 13mV ) 8.6 Failed in Q.A. Did not reach end user
C44611-R22AV	947093	0058544	Output ( 9mV - 13mV ) 8.8 Failed in Q.A. Did not reach end user
C44611-R22AV	947097	0058544	Output ( 9mV - 13mV ) 8.1 Failed in Q.A. Did not reach end user
C44611-R22AV	947108	0058544	Output ( 9mV - 13mV ) 17.4 Failed in Q.A. Did not reach end user
C44611-R22AV	947113	0058544	Output ( 9mV - 13mV ) 8.7 Failed in Q.A. Did not reach end user
C44611-R22AV	947154	0058544	Output ( 9mV - 13mV ) 8.9 Failed in Q.A. Did not reach end user
C44611-R22AV	947207	0058544	Output ( 9mV - 13mV ) 8.1 Failed in Q.A. Did not reach end user
C44611-R22AV	947491	0058544	Output ( 9mV - 13mV ) 7.8 Failed in Q.A. Did not reach end user