

Viamed Returns Shipping Invoice

Delivery Address:
Teledyne Analytical Instruments
Margie Read
16830 Chestnut Street
City Of Industry
California
91748-1020
0016269341589

Date: 17 Sep 2025
RMA:
Viamed RN: RTS1100932

Shipper Address:
Viamed
15 Station Road
Cross Hills
Keighley
West Yorkshire
BD20 7DT
+44 (0) 1535 634542
+44 (0) 1535 635582
info@viamed.co.uk

Part Number	P/N / Value	Description	Quantity
C43690-R17A	0110117 (\$27.00) Tariff Code: HTS Code 9027.10.2000 Country of Origin: USA	Automotive Oxygen Sensor R-17A	2
C43690-R17AH	0110137 (\$33.00) Tariff Code: HTS Code 9027.10.2000 Country of Origin: USA	Automotive Oxygen Sensor R-17A	5
C44611-R22A	0110122 (\$20.00) Tariff Code: HTS Code 9027.10.2000 Country of Origin: USA	Automotive Oxygen Sensor R-22A	6

Part Number	Serial Number	RMA	Fault Description
C43690-R17A	880747		Output (7mV - 13mV) 13.5mV Failed in Q.A. Did not reach end user
C43690-R17A	880778		Output (7mV - 13mV) 14.1mV Failed in Q.A. Did not reach end user
C44611-R22A	957112		Output (7mV - 13mV) 4.3mVFailed in Q.A. Did not reach end user
C44611-R22A	957114		Output (7mV - 13mV) 5.3mV Failed in Q.A. Did not reach end user
C44611-R22A	957360		Output (7mV - 13mV) 2.9mV Failed in Q.A. Did not reach end user
C44611-R22A	958316		Output (7mV - 13mV) 41.9-11.9 erratic Failed in Q.A. Did not reach end user
C44611-R22A	970583		Output (7mV - 13mV) Leaking Failed in Q.A. Did not reach end user
C44611-R22A	970818		Output (7mV - 13mV) 00.1 Failed in Q.A. Did not reach end user
C43690-R17AH	983731		Output (10.5mV - 13.5mV) 14.1 Failed in Q.A. Did not reach end user
C43690-R17AH	983785		Output (10.5mV - 13.5mV) 15.6 Failed in Q.A. Did not reach end user
C43690-R17AH	983838		Output (10.5mV - 13.5mV) 13.9mV Failed in Q.A. Did not reach end user
C43690-R17AH	983843		Output (10.5mV - 13.5mV) 10.3mV Failed in Q.A. Did not reach end user
C43690-R17AH	983857		Output (7mV - 13mV) 14.0mV failed in QA did not reach end user