

# VST Returns Shipping Invoice

**Delivery Address:**

Honeywell Healthcare Solutions GmbH RMA:

Karen Bull

Alter Holzhafen 18

Wismar

Germany

D-23966

Eori DE3174778

0049 3841 360204

Date: 08 Jan 2026

VST RN: RTS31001061

**Shipper Address:**

VST

15 Station Road

Cross Hills

Keighley

West Yorkshire

BD20 7DT

+44 (0) 1535 634900

+44 (0) 1535 635582

info@vandagraphst.com

---

Returns Under Warranty Value for Customs : 5.00 EuroSee Attached Listing for Serial numbers and Faults

---

| Part Number | P/N / Value                        | Description            | Quantity |
|-------------|------------------------------------|------------------------|----------|
| 8010026     | 8010026<br>Tariff Code: 9019209000 | Oxygen Sensor - MDS100 | 1        |
| 8010018     | 8010018<br>Tariff Code: 9019209000 | Oxygen Sensor - T22D   | 1        |
| 8010007     | 8010007<br>Tariff Code: 9019209000 | Oxygen Sensor - NaNS01 | 1        |

| Part Number | Serial Number | RMA | Fault Description                                                                                             |
|-------------|---------------|-----|---------------------------------------------------------------------------------------------------------------|
| 8010007     | S01121399     |     | Electrolyte Leakage                                                                                           |
| 8010018     | M3S105735     |     | Low Output                                                                                                    |
| 8010026     | SR101112      |     | Unstable output signal. Output drops when cell is tilted. Country of Origin: Germany Customs Value: 5.00 euro |

| Part Number | Serial No. | RMA | Fault Report |
|-------------|------------|-----|--------------|
| 8010007     | S01121399  |     |              |
| 8010018     | M3S105735  |     |              |
| 8010026     | SR101112   |     |              |