



Showing From :01 Jul 2017

QA Review - Failures

Check the Previous Months Figures, First number is quantity Failed QA, Second is the number that have passed through QA, and the Final number is the Percentage of units Failing QA.

Raise a non Conformance report for any where the % is Greater than 5%

Stock Reference	Description	Jul 2017	Aug 2017	Sep 2017	Oct 2017	Nov 2017	Dec 2017	
0110107	Oxygen sensor - Automotive R-17A-LV	1 / 100 1.00%	Examine 8 / 8 100.00%	0 /	0 /	Examine 12 / 300 4.00%	0 /	Raise Non Conformance review
0110017	Oxygen sensor R-17MED	1 / 521 0.19%	0 / 196	0 / 83	Examine 1 / 12 8.33%	4 / 674 0.59%	Examine 10 / 300 3.33%	Raise Non Conformance review
0110022	Oxygen sensor R-22MED	0 / 145	1 / 253 0.40%	0 / 5	0 / 295	0 / 61	0 / 233	Raise Non Conformance review
0110132	Oxygen sensor - Automotive R-22AV	0 / 500	0 /	1 / 627 0.16%	13 / 1808 0.72%	0 / 91	Examine 11 / 426 2.58%	Raise Non Conformance review
0110137	Oxygen sensor - Automotive R-17AH	0 /	0 / 3	0 /	Examine 1 / 9 11.11%	Examine 17 / 94 18.09%	Examine 2 / 6 33.33%	Review Issue Issue 109600
0110117	Oxygen sensor - Automotive R-17A	0 /	0 / 1	0 /	0 / 8	Examine 4 / 120 3.33%	0 /	Raise Non Conformance review
0110127	Oxygen sensor - Automotive R-17AV	0 / 50	0 /	0 /	0 / 7	Examine 15 / 175 8.57%	0 /	Review Issue Issue 109601
4410500	Capnograph VM-2500-M	0 / 12	0 / 3	0 / 10	0 / 5	Examine 1 / 10 10.00%	0 /	Review Issue Issue 109602
0012105	Finger Pulse Oximeter Viamed VM 2105.	0 /	0 / 1	0 /	0 /	Examine 1 / 20 5.00%	0 / 30	Review Issue Issue 109603
0110122	Oxygen sensor - Automotive R-22A	0 / 1	0 / 43	0 /	0 / 660	1 / 415 0.24%	4 / 410 0.98%	Raise Non Conformance review
0110361	Oxygen sensor R-22AHJR Jikco OEM sensor	0 /	0 / 3	0 / 319	0 /	0 /	Examine 4 / 171 2.34%	Raise Non Conformance review
0110349	Oxygen sensor R21AV. HAIK OEM sensor.	0 /	0 /	0 / 100	0 /	0 /	Examine 4 / 100 4.00%	Raise Non Conformance review
0012106	Finger Pulse Oximeter Viamed VM 2105.	0 /	0 /	0 /	0 /	0 /	Examine 50 / 50	Review Issue Issue 111252

100.00%