

⭐ 📲 📈 1 🔍 📜 📚 📈 Derek Lamb 158 Issues 5 Unread | Imported 04 Feb 07:56:53 | Holiday Requests | Out of Office: Future



Repairs not Closed from the system

KEY

Not chased or Reviewed +2 Weeks

Not chased or Reviewed +1 Week

Been chased or Reviewed within 1 Week

Notes, Status and Chased Dates are NOT to be confused with the actual repair notes, repair status or anything within the SRS itself.

They are designed to be independent to the repair but as an overview of where the repair is in relation to our system.

SRS	SOR		Account	Name	Quote	Goods Received	Been Received No engineer Action	Been Received Engineer Action	Ready For Quote	Quote been Sent	Quote Received and Declined	Quote Received and Accepted	Complete but not Invoiced / Matched
SRS66919	+ Vandagraph				QUO	✓ 28/Jan/19		✓					
Notes											Status	Normal	28 Jan 2019
SRS	SOR		Account	Name	Quote	Goods Received	Been Received No engineer Action	Been Received Engineer Action	Ready For Quote	Quote been Sent	Quote Received and Declined	Quote Received and Accepted	Complete but not Invoiced / Matched
SRS66904	+ Vandagraph		V000070		QUO	✓ 17/Jan/19		✓					✓
Notes											Status	Normal	17 Jan 2019
SRS	SOR		Account	Name	Quote	Goods Received	Been Received No engineer Action	Been Received Engineer Action	Ready For Quote	Quote been Sent	Quote Received and Declined	Quote Received and Accepted	Complete but not Invoiced / Matched
SRS66875	+ Vandagraph				QUO	✓ 24/Dec/18	✓						
Notes											Status	Normal	24 Dec 2018
SRS	SOR		Account	Name	Quote	Goods Received	Been Received No engineer Action	Been Received Engineer Action	Ready For Quote	Quote been Sent	Quote Received and Declined	Quote Received and Accepted	Complete but not Invoiced / Matched
SRS66858	+ Vandagraph				QUO	✓ 12/Dec/18		✓					✓
Notes											Status	Normal	12 Dec 2018
SRS	SOR		Account	Name	Quote	Goods Received	Been Received No engineer Action	Been Received Engineer Action	Ready For Quote	Quote been Sent	Quote Received and Declined	Quote Received and Accepted	Complete but not Invoiced / Matched
SRS66847	+ Vandagraph				QUO	✓ 10/Dec/18		✓					✓
Notes											Status	Normal	10 Dec 2018
SRS	SOR		Account	Name	Quote	Goods Received	Been Received No	Been Received	Ready For Quote	Quote been Sent	Quote Received and Declined	Quote Received and Accepted	Complete but not

							Engineer Action	Engineer Action		and Declined		Invoiced / Matched	
SRS66839	+	Vandagraph	VOBSTER		QUO	✓05/Dec/18		✓				✓	
Notes													
SRS	SOR		Account	Name	Quote	Goods Received	Been Received No engineer Action	Been Received Engineer Action	Ready For Quote	Quote been Sent	Quote Received and Declined	Quote Received and Accepted	Complete but not Invoiced / Matched
SRS66444	+	Vandagraph			QUO	✓13/Mar/18	✓						
Notes													

Stock References Live in the System

Details	Stock ref	Description	Number In System
Details	0110217	Oxygen sensor R-17VAN	4
Details	0110224	Oxygen sensor R-33DE	1
Details	Mixchek		1
Details	7910211	Oxygen Analyser Tek-Ox + Quick-Ox	1
Details	9711600	Mixchek Helium/Oxygen Analyser	1

Customers in the System (Only showing returns actually received, not SRS numbers allocated)

	Account	Name
Details		
Details	V000070	
Details	VOBSTER	