

Service Repair Sheet 67825

Contact Name Jim McKay  
Company/ Hospital Name JFD  
Date Received 12/May/2021  
Booked in By Robert Connor

---

Repair Ref S/N      Equipment Type      Under Warranty  
SRN33676 8010050 102374      Oxygen Sensor VST

Replaced  
Time :0 Hour(s)

No output replaced under warranty

---