

Service Repair Sheet 67831

Contact Name	Paul Raymaekers
Company/ Hospital Name	rEvo
Direct Phone	0032 50454405
Opera Account	VST006
Email	info@revo-rebreathers.com
Date Received	12/May/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN33672	8010006	002133911	Oxygen Sensor VST	Replaced Time :0 Hour(s)

Out of warranty, replaced as good will gesture

Repair	Ref	S/N	Equipment Type		Under Warranty
SRN33673	8010006	009134948	Oxygen Sensor VST	Replaced Time :0 Hour(s)	

No output replaced under warranty

Repair	Ref	S/N	Equipment Type		Under Warranty
SRN33674	8010006	011136828	Oxygen Sensor VST	Replaced Time :0 Hour(s)	

No output replaced under warranty

Repair	Ref	S/N	Equipment Type		Under Warranty
SRN33675	8010006	012137363	Oxygen Sensor VST	Replaced Time :0 Hour(s)	

No output replaced under warranty
