

# Viamed Returns Shipping Invoice

Delivery Address:  
Teledyne Analytical Instruments  
Vasu Narasimhan  
16830 Chestnut Street

Date: 09 Sep 2021  
RMA:  
Viamed RN: RTS1100812

Shipper Address:  
Viamed  
15 Station Road  
Cross Hills  
Keighley  
West Yorkshire  
BD20 7DT  
+44 (0) 1535 634542  
+44 (0) 1535 635582  
info@viamed.co.uk

91748-1020

0016269341589

---

Returns Under Warranty Value for Customs : \$100.00  
See Attached Listing for Serial numbers and Faults

---

Part Number	P/N / Value	Description	Quantity
C43690-R17MED	0110017 (\$23.00) Tariff Code: 9019200000 Country of Origin: USA	Oxygen sensor, R17MED	13
C44611-R22MED	0110022 (\$23.00) Tariff Code: 9019200000 Country of Origin: USA	Oxygen sensor, R22MED	9
C61339-R23MED	0110023 Tariff Code: 9019200000	Oxygen sensor, R23	1

Part Number	Serial Number	RMA	Fault Description
C43690-R17MED	465227		Unstable
C43690-R17MED	524654		Fluctuating O/p - During Use
C43690-R17MED	524655		Fluctuating O/p - During Use
C43690-R17MED	554239		Non Linear
C43690-R17MED	571933		Connector Fault
C43690-R17MED	601211		Connector Fault
C43690-R17MED	646428		Output ( 7mV - 13mV ) 12.4 n Pass Yes n Move Item to location 126559 n Output ( 7mV - 13mV ) 13.3 n Move Item to location 126559 n Failed in Q.A. n Did not reach end user
C43690-R17MED	646438		Output ( 7mV - 13mV ) 13.4 n Move Item to location 126559 n Output ( 7mV - 13mV ) 13.4 n Move Item to location 126559 n Failed in Q.A. n Did not reach end user
C43690-R17MED	646440		Output ( 7mV - 13mV ) 13.4 n Move Item to location 126559 n Failed in Q.A. n Did not reach end user
C43690-R17MED	646457		Output ( 7mV - 13mV ) 13.5 n Move Item to location 126559 n Failed in Q.A. n Did not reach end user
C43690-R17MED	646461		Output ( 7mV - 13mV ) 13.2 sensor doesnt fit on tester very loose. n Move Item to location 126559 n Failed in Q.A. n Did not reach end user
C43690-R17MED	646467		Output ( 7mV - 13mV ) 1823656 n Pass Yes n Move Item to location 126559 n Output ( 7mV - 13mV ) 13.6 n Move Item to location 126559 n Failed in Q.A. n Did not reach end user
C43690-R17MED	646471		Output ( 7mV - 13mV ) 00.1 n Move Item to location 126559 n Failed in Q.A. n Did not reach end user
C44611-R22MED	473358		Unstable
C44611-R22MED	582573		Output ( 7mV - 13mV ) 12.9 n Pass Yes n Move Item to location 126560 n Output ( 7mV - 13mV ) 14.0 n Move Item to location 126560 n Failed in Q.A. n Did not reach end user
C44611-R22MED	589356		Output ( 7mV - 13mV ) 11.0 n Pass Yes n Move Item to location 126560 n Output ( 7mV - 13mV ) 00.3 n Move Item to location 126560 n Failed in Q.A. n Did not reach end user
C44611-R22MED	589364		Output ( 7mV - 13mV ) 12.7 n Pass Yes n Move Item to location 126560 n Output ( 7mV - 13mV ) 13.6 n Move Item to location 126560 n Failed in Q.A. n Did not reach end user
C44611-R22MED	589378		Output ( 7mV - 13mV ) 9.6 n Pass Yes n Move Item to location 126560 n Output ( 7mV - 13mV ) 00.3 n Move Item to location 126560 n Failed in Q.A. n Did not reach end user
C44611-R22MED	589382		Output ( 7mV - 13mV ) 10.5 n Pass Yes n Move Item to location 126560 n Output ( 7mV - 13mV ) 00.7 n Move Item to location 126560 n Failed in Q.A. n Did not reach end user
C44611-R22MED	589385		Output ( 7mV - 13mV ) 9.9 n Pass Yes n Move Item to location 126560 n Output ( 7mV - 13mV ) 5.6 n Move Item to location 126560 n Output ( 7mV - 13mV ) 5.5 n Move Item to location 126560 n Failed in Q.A. n Did not reach end user
C44611-R22MED	589419		Output ( 7mV - 13mV ) 10.0 n Pass Yes n Move Item to location 126560 n Output ( 7mV - 13mV ) 01.4 n Move Item to location 126560 n Failed in Q.A. n Did not reach end user
C44611-R22MED	597205		Unstable
C61339-R23MED	V121059		Unstable