

Viamed Returns Shipping Invoice

Delivery Address:
Teledyne Analytical Instruments
Margie Read
16830 Chestnut Street
City Of Industry
California
91748-1020
0016269341589

Date: 25 Mar 2022
RMA:
Viamed RN: RTS1100864

Shipper Address:
Viamed
15 Station Road
Cross Hills
Keighley
West Yorkshire
BD20 7DT
+44 (0) 1535 634542
+44 (0) 1535 635582
info@viamed.co.uk

Returns Under Warranty Value for Customs : \$100.00
See Attached Listing for Serial numbers and Faults

Part Number	P/N / Value	Description	Quantity
C43690-R17A	0110117 (\$16.00) Tariff Code: HTS Code 9027.10.2000 Country of Origin: USA	Automotive Oxygen Sensor R-17A	2
C43690-R17AV	0110127 (\$16.00) Tariff Code: HTS Code 9027.10.2000 Country of Origin: USA	Automotive Oxygen Sensor R-17A	1
C43690-R17AH	0110137 (\$16.00) Tariff Code: HTS Code 9027.10.2000 Country of Origin: USA	Automotive Oxygen Sensor R-17A	1
C44611-R22AHJR	0110361 (\$16.50) Tariff Code: HTS Code 9027.10.2000 Country of Origin: USA	Oxygen sensor R-22AHJR Jikco	2

Part Number	Serial Number	RMA	Fault Description
C43690-R17A	601054		Output (7mV - 13mV) 15.4 Failed in Q.A. n Did not reach end user
C43690-R17A	601125		Output (7mV - 13mV) 13.6 Failed in Q.A. n Did not reach end user
C43690-R17AV	778111		Output (9mV - 13mV) 13.8 Failed in Q.A. n Did not reach end user
C43690-R17AH	697218		Output (10.5mV - 13.5mV) 10.4 Failed in Q.A. n Did not reach end user
C44611-R22AHJR	A771170		Output (10.5 - 13.5 mV) 10.4 Failed in Q.A. n Did not reach end user
C44611-R22AHJR	A771192		Output (10.5 - 13.5 mV) 10.4 Failed in Q.A. n Did not reach end user