

Invoice Correction 5259313078

ORIGINAL

Invoice Correction Date: 04.03.2022

Honeywell Healthcare Solutions GmbH

Alter Holzhafen 18

Purchase Order No: RTS3100844

23966 Wismar

Germany

Bill to: 1797471

Vandagraph Limited
15 Station Road
Cross Hills, West Yorkshire
BD20 7DT
KEIGHLEY
United Kingdom

Sold to: 1797448

Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom

Order Information:

Credit Memo Request: 63813808
Sales Office: 2170 DE SPS Wismar
Incoterms: FCA Origin
Payment Terms: Net 30 Days After Invoice Date

Ship to: 1797448

Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom

ITEM NO.	Material No.	QTY	UOM	UNIT PRICE	EXT. PRICE	VAT %
000010	E1001581 Oxygen Sensor OOD103-1V Customer Part Nbr: 8010007 credit note for SN: 114189	1	EA	20.00 ✓	-20.00	0%
000020	E1001721 Oxygen Sensor OOD103-2V Customer Part Nbr: 8010004 credit note for SN: 134205	1	EA	20.73 <i>Should be 26.73€ each.</i>	-20.73	0%

Totals

Total Before VAT -40.73 EUR
VAT-Total 0.00 EUR
Total Amount -40.73 EUR

Tax Information

Tax Exempt Reason: Tax free export - Goods

Integrity and Compliance at Honeywell

Honeywell places the highest value on the integrity of its business operations. We expect our employees and business partners to comply with our Code of Business Conduct and all applicable laws and regulations. If you become aware of illegal or improper conduct by a Honeywell employee please contact your Honeywell relationship manager. You can also report misconduct directly to us either via e-mail to our Integrity and Compliance Office at access.integrity.helpline@honeywell.com or via our Access helpline accessible worldwide at 800-237-5982.

Duns #:

Bank Details: No Payment Due

Account Name:

Account No:

Bank Key:

Swift Code:

IBAN:

Payment method:

Registered No: Schwerin HRB 1838

VAT Reg No: DE137437213

Federal ID #:

Registered Address: Honeywell Healthcare Solutions GmbH, Alter Holzhafen 18, Wismar, 23966, Germany

Credit Analyst: Xenia Musat

Sales Rep: Stefan Dreyer

Customer Care Rep: Jessica Wagner +49 3841 360 206

Honeywell Healthcare Solutions GmbH

WEEE Reg.No.: 57798680

Internet: www.envitec.com

Managing Director: Marcus Ostlander

email: info@envitec.com


Delivery exclusive to our General Terms (February 2016). We retain title to our goods and deliveries until all the payment from the sales contract have been received. Your order will be executed exclusively to our terms and conditions. These can be sent by separate request or viewed at www.envitec.com

Kunde/ Customer	Vandagaph	Retour/ RMA- No.	Kunde/Customer	PTS 3100844	EnviteC	300248181
Artikel/ Article	000 103-1V; 000103-2V	Anzahl/ Quantity		1;1	Eing. Datum/ Inc. Date	08.02.22
Bearbeitet/ processed	Buer	Prüfdatum/ Insp. Date		16.02.22	Geprüft/ Inspected	Buer

Nr.	Produkt/ Identification		Messwert/ Test Result				Bemerkung/ Remark	Bewertung/ Evaluation			
	Seriennummer/ Serial no.	Lieferlos/ Manufact. code	Luftwert/ Air signal @ 20,9% O ₂ [mV]	Nullsignal/ Offset @ 0% O ₂ [µV]	Linearität/ Linearity [%]	außerhalb Garantie/ out of warranty		kein Fehler festgestellt/ no failure found	Fehlercode/ Failure- code	Austausch / Replacement	
1	114189	03121	11.5	26	i.o.	Drucktest			07		
2	134205	10121	11.9	31	i.o.	Drucktest			07		
3											
4											
5											
6											
7											
8											
9											
10											
11											
12											
13											
14											
15											
16											
17											
18											
19											
20											

Fehler O2-S001: Luftwert außerhalb Toleranz/ Air signal out of tolerance
 Fehler O2-S003: Offset außerhalb Toleranz/ Offset out of tolerance
 Fehler O2-S005: Gehäuse defekt/ Housing defective
 Fehler O2-S007: Sonstiges (unter Angabe in Bemerkung) / Others (see remark)

Fehler O2-S002: Signal instabil / Signal not stable
 Fehler O2-S004: Signal 0mV / Signal 0mV
 Fehler O2-S006: Elektrolyt Austritt / Electrolyte leakage



BOX:844

Manufacturer RMA : 300249181

☒ Repaired
 ☐ No Fault Found

Returned Barcode

Tick All Replaced

Stock Ref	Sup Ref	B/C	S/N	Fault	Replaced	No Fault Found	Repaired	Credited	Out Warranty	Notes
8010004		1852103	JJ134205	Unknown fault Country of Origin: Germany Customs Value :5.00 euro	☐	☐	☐	☒	☐	
8010007		1703462	S01114189	Unknown fault Country of Origin: Germany Customs Value :5.00 euro	☐	☐	☐	☒	☐	

Update