

Viamed Returns Shipping Invoice

Delivery Address:
Teledyne Analytical Instruments
Margie Read
16830 Chestnut Street
City Of Industry
91748-1020

Date: 30 Sep 2022
RMA:
Viamed RN: RTS1100839

Shipper Address:
Viamed
15 Station Road
Cross Hills
Keighley
West Yorkshire
BD20 7DT
+44 (0) 1535 634542
+44 (0) 1535 635582
info@viamed.co.uk

Part Number	P/N / Value	Description	Quantity
C44611-R22A	0110122 (\$16.00)	Automotive Oxygen Sensor R-22A	5
	Tariff Code: HTS Code 9027.10.2000		
	Country of Origin: USA		
C43690-R17AH	0110137 (\$16.00)	Automotive Oxygen Sensor R-17A	3
	Tariff Code: HTS Code 9027.10.2000		
	Country of Origin: USA		
C44611-R22AHJR	0110361 (\$16.50)	Oxygen sensor R-22AHJR Jikco	2
	Tariff Code: HTS Code 9027.10.2000		
	Country of Origin: USA		

Part Number	Serial Number	RMA	Fault Description
C44611-R22A	664992		Low Output 2.6mV Failed in Q.A. Did not reach end user
C44611-R22A	665085		No Output 00.1mV Failed in Q.A. Did not reach end user
C44611-R22A	665124		Low Output 5.3mV Failed in Q.A. n Did not reach end user
C44611-R22A	668990		High Output 23.5 Failed in Q.A. n Did not reach end user
C44611-R22A	693147		Low Output 6.4mV Failed in Q.A.Did not reach end user
C43690-R17AH	697092		No Output 00.1mV Failed in Q.A. Did not reach end user
C43690-R17AH	697102		High Output 14.5mV Failed in Q.A. Did not reach end user
C43690-R17AH	697227		Low Output 10.3mV Failed in Q.A. Did not reach end user
C44611-R22AHJR	A695163		Low Output 9.8mV failed in Q/A did not reach end user
C44611-R22AHJR	A695167		Low Output 8.6 mV Failed in Q.A. Did not reach end user