


Derek Lamb 73 Issues **6 Unread** 15 ISO Tasks | [New Holiday 18.00 °C](#)

Menu Item

Search



SN Full, SH Full, EH Full



Showing From :01 Oct 2022

QA Review - Failures

Check the Previous Months Figures, First number is quantity Failed QA, Second is the number that have passed through QA, and the Final number is the Percentage of units Failing QA.
Raise a non Conformance report for any where the % is Greater than 5%

Stock Reference	Description	Oct 2022	Nov 2022	Dec 2022	Jan 2023	Feb 2023	Mar 2023	Apr 2023	May 2023	Jun 2023	Jul 2023	Aug 2023	Sep 2023	
0110361	Oxygen sensor R-22AHJR Jikco OEM sensor	Examine 15 / 120 12.50%	Examine 2 / 59 3.39%	0 /	Examine 40 / 271 14.76%	0 /	0 /	0 /	1 / 200 0.50%	0 /	0 /	Examine 2 / 31 6.45%	Examine 49 / 317 15.46%	Raise Non Conformance review
0110107	Oxygen sensor - Automotive R-17A-LV	2 / 100 2.00%	0 /	0 /	0 /	0 / 51	0 /	Examine 1 / 49 2.04%	0 /	0 /	0 /	0 /	0 /	Raise Non Conformance review
0110117	Oxygen sensor - Automotive R-17A	Examine 3 / 39 7.69%	0 /	0 /	0 /	Examine 4 / 55 7.27%	1 / 100 1.00%	0 /	0 /	0 /	2 / 100 2.00%	0 /	0 /	Raise Non Conformance review
0110132	Oxygen sensor - Automotive R-22AV	1 / 498 0.20%	0 / 720	0 / 277	0 /	0 / 266	2 / 234 0.85%	0 / 498	7 / 641 1.09%	0 / 359	0 / 150	0 / 140	1 / 910 0.11%	Raise Non Conformance review

0110122	Oxygen sensor - Automotive R-22A	3 / 800 0.38%	4 / 333 1.20%	0 / 167	0 /	0 / 699	1 / 1198 0.08%	0 /	0 /	5 / 1561 0.32%	0 / 654	3 / 860 0.35%	1 / 963 0.10%	Raise Non Conformance review
0110024	Oxygen sensor R-24MED	0 /	1 / 106 0.94%	0 /	0 /	0 /	0 /	0 /	1 / 100 1.00%	1 / 100 1.00%	0 /	0 /	0 /	Raise Non Conformance review
2810011	MD300-C2 Finger Pulse Oximeter.	0 /	Examine 1 / 2 50.00%	0 / 149	0 / 100	0 /	0 /	0 /	0 /	0 /	0 /	0 /	0 /	Raise Non Conformance review
0014750	SpO2 Silicone Finger Sensor - Adult.	0 /	Examine 1 / 2 50.00%	0 /	0 /	0 /	0 /	0 /	0 /	0 /	0 /	0 /	0 /	Raise Non Conformance review
0014650	SpO2 Finger Sensor - Adult.	0 /	Examine 1 / 3 33.33%	0 /	0 /	0 /	0 /	0 /	0 /	0 /	0 /	0 /	0 /	Raise Non Conformance review
2810046	MD300-C15D - Green Finger Pulse Oximeter	0 /	Examine 1 / 1 100.00%	0 /	0 /	0 /	0 /	0 /	0 /	0 /	0 /	0 /	0 /	Raise Non Conformance review
0015000	Pulse oximetry Lingual Sensor	0 /	Examine 2 / 2 100.00%	0 /	0 /	0 /	0 /	0 /	0 /	0 /	0 /	0 /	0 /	Raise Non Conformance review
0110121	Oxygen sensor - Automotive R-21A	0 /	0 / 74	0 /	1 / 151 0.66%	0 / 113	0 /	1 / 300 0.33%	0 /	0 /	0 / 25	0 / 114	0 / 11	Raise Non Conformance review
0110022	Oxygen sensor R-22MED	0 /	0 /	0 / 2	1 / 399 0.25%	0 /	0 /	3 / 800 0.38%	0 /	Examine 13 / 300 4.33%	0 /	0 /	0 /	Raise Non Conformance review
0110017	Oxygen sensor R-17MED	0 /	0 /	0 /	0 / 260	3 / 571 0.53%	0 / 58	2 / 298 0.67%	0 /	0 / 299	0 /	0 /	0 /	Raise Non Conformance review
0110127	Oxygen sensor -	0 /	0 /	0 /	0 /	0 /	0 /	2 / 200 1.00%	0 /	0 /	0 /	0 /	0 /	Raise Non Conformance review

	Automotive R-17AV													
0110137	Oxygen sensor - Automotive R-17AH	0 / 100	0 /	0 /	0 /	0 / 100	0 /	Examine 6 / 100 6.00%	0 /	0 /	0 /	Examine 4 / 163 2.45%	Examine 5 / 56 8.93%	Raise Non Conformance review
0111275	Oxygen analyser OxiQuant S	0 /	0 /	0 /	0 / 20	0 / 38	0 / 20	0 / 15	0 /	0 / 49	0 / 50	1 / 50 2.00%	0 /	Raise Non Conformance review